

Wampatuck Elementary School

266 Tilden Road
Scituate, Massachusetts 02066

3-Year AHERA Reinspection May 2024

PREPARED FOR:

Scituate Public Schools
606 Chief Justice Cushing Highway
Scituate, Massachusetts 02066

PREPARED BY:

The VERTEX Companies, LLC
400 Libbey Parkway
Weymouth, Massachusetts 02189

Table of Contents

- Section 1 - Introduction
 - Bulk Sampling Methodology
 - Updated Homogeneous Area Hazard Assessment
- Section 2 - Response Action Determination
- Section 3 - Updated Recommended Response Actions
- Section 4 - Recordkeeping Requirements and Recommendations
- Section 5 - Estimated Resources Needed to Complete Response Actions
- Section 6 - Estimated Resources Required for the Abatement of the Identified ACMs
- Section 7 - Operations and Maintenance

Appendices

- Appendix A - Locations of the ACMs and Updated Conditions
- Appendix B - Estimated Costs to Needed to Complete the Response Actions
- Appendix C - Estimated Costs to for Abatement of the Identified ACMs
- Appendix D - Personnel Certifications
- Appendix E - Schematic
- Appendix F - Six-Month Surveillance Forms
- Appendix G - Designated Person Assurances

Introduction

The Vertex Companies, LLC. (VERTEX) conducted a 3-Year Re-inspection on May 31, 2022 as required by the 40 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) at the Wampatuck Elementary School located at 266 Tilden Road in Scituate, Massachusetts. The AHERA regulation requires that each Local Education Agency (LEA) retain a certified/accredited Asbestos Inspector to conduct an initial inspection of all friable and non-friable known or assumed asbestos-containing materials (ACMs) in each school building that they lease, own, or otherwise uses as a school building. The AHERA re-inspection is to be performed by an accredited inspector at least once every three years from the time of implementation of the original management plan. In addition, the LEA is responsible for conducting Six-Month Periodic Surveillance Inspections as required to effectively manage the identified ACMs in place at the school.

The Scituate Public School District may utilize the information obtained from the AHERA inspection to effectively manage the ACMs identified at the Wampatuck Elementary School.

SECTION 1
INSPECTION REPORT

Section 1
Inspection Report

Inspection Protocol

Massachusetts Department of Labor Standards (DLS) Certified Asbestos Inspector, Jason Mohre (AI#000262) performed the AHERA inspection. The Management Plan was updated by Massachusetts DLS Certified Asbestos Management Planner, Jason Mohre (AP#000080). The purpose of the inspection was to identify friable and non-friable ACMs and perform a hazard assessment. As required by the AHERA regulation, the inspection survey procedures must include a visual inspection and assessment of the condition of all known locations of friable and non-friable ACMs. It should be noted that under the AHERA regulations only ACMs are inspected within the school building, other asbestos containing materials (ACMs) may be associated with the school that do not fall under AHERA ACM definition. Examples of materials which have been found to contain asbestos include but are not limited to exterior window caulking, window glazing, and roofing material. Prior to school renovations any suspect materials not sampled or listed within the school's AMP, must be tested prior to disturbance. Furthermore, VERTEX recommends an Asbestos Containing Materials (ACMs) Survey be conducted prior to any renovation activities to comply with the Environmental Protection Agency (EPA) Title 40 CFR Part 61, National Emissions Standards for Hazardous Air Pollutants (NESHAPs) and the Massachusetts Department of Environmental Protection Regulations. Documentation for subsequent surveys not related to AHERA should be included in the overall Management Plan.

Assessment of potential asbestos hazards are subject to each individual inspector's judgment, and as a result, hazard assessments may vary.

Furthermore, the LEA Designated Person should assume that potential asbestos-containing pipe and fitting insulation or other ACMs may be located behind walls and ceilings not accessible. Any renovation/demolition work that may penetrate these areas should be inspected prior to disturbance.

All available documentation of asbestos abatement projects, which have occurred since the initial AHERA inspection should be included with the Management Plan for the school.

VERTEX was provided and reviewed the following documents for the Wampanatuck Elementary School facility:

- AHERA Inspection and Management Plan for the Wampanatuck Elementary School prepared by Covino, dated November 2013.
- AHERA Inspection and Management Plan the Wampanatuck Elementary School prepared by TRC, dated October 2017.

Appendix D contains Certification Page for the Inspector and Management Planner involved with the inspection of the school.

Locations of the identified ACMs with quantities observed, conditions assessed, homogeneous hazard assessment are presented in Appendix A of this report.



Section 1
Inspection Report (continued)
Bulk Sampling Methodology

Bulk samples were not collected during the current reinspection. VERTEX had collected and analyzed the following bulk samples of suspect homogeneous materials within school during past inspection in April 2021. In addition, Covino Environmental (Covino) collected bulk samples during their August 2013 inspection activities. Please refer to Table 1A and 1B below for a summary of the bulk samples collected and analyzed.

Wampatuck Elementary School
April 2021 Sample Locations and Results
Table IA

Sample Number	Sample Description	Sample Location	Asbestos Content
B-422-01A	12" Off-White Spec Floor Tile	Room 222	5 % Chrysotile
B-422-01B	12" Off-White Spec Floor Tile	Room 208	Positive Stop
B-422-02A	Black Floor Tile Mastic	Room 222	10 % Chrysotile
B-422-02B	Black Floor Tile Mastic	Room 208	Positive Stop
B-422-03A	12" Black Dark Brown Spec Floor Tile	Room 222	5 % Chrysotile
B-422-03B	12" Black Dark Brown Spec Floor Tile	Room 208	Positive Stop

**Wampatuck Elementary School
 August 2013 Sample Locations and Results**

Table IB

Sample Number	Sample Description	Sample Location	Asbestos Content
1A	Pipe Insulation	Hallway	40 % Chrysotile 10% Crocidolite
1B	Pipe Insulation	Kitchen Office	Positive Stop
1C	Pipe Insulation	Room 146	Positive Stop
2A	Pipe Fitting Insulation	Storage Room	None Detected
2B	Pipe Fitting Insulation	Room 146	8 % Chrysotile
2C	Pipe Fitting Insulation	Hall at Office	Positive Stop
2D	Pipe Fitting Insulation	Room 2	Positive Stop
2E	Pipe Fitting Insulation	Room 1	Positive Stop
2F	Pipe Fitting Insulation	Room 13	Positive Stop
2G	Pipe Fitting Insulation	Room 15	Positive Stop
3A	12" Multi-Color Floor Tile	Office	None Detected
3B	12" Multi-Color Floor Tile	Hall at Storage	None Detected
3C	12" Multi-Color Floor Tile	Hall by Office	None Detected
4A	12" Multi-Color Floor Tile Mastic	Office	None Detected
4B	12" Multi-Color Floor Tile Mastic	Hall at Storage	None Detected
4C	12" Multi-Color Floor Tile Mastic	Hall by Office	None Detected
5A	9" Brown Floor Tile	Storage Room	8 % Chrysotile
5B	9" Brown Floor Tile	Receiving Storage Room	Positive Stop
5C	9" Brown Floor Tile	Teachers Room	Positive Stop
6A	9" Brown Floor Tile Mastic	Storage Room	None Detected
6B	9" Brown Floor Tile Mastic	Receiving Storage Room	None Detected
6C	9" Brown Floor Tile Mastic	Teachers Room	None Detected
7A	Plaster Ceiling Base Coat	Storage Room	None Detected
7B	Plaster Ceiling Base Coat	Receiving Storage Room	None Detected
7C	Plaster Ceiling Base Coat	Room 146	None Detected
7D	Plaster Ceiling Base Coat	Room 6	None Detected
7E	Plaster Ceiling Base Coat	Room 119	None Detected
7F	Plaster Ceiling Base Coat	Room 13	None Detected
7G	Plaster Ceiling Base Coat	Room 15	None Detected

Wampatuck Elementary School
August 2013 Sample Locations and Results
Table I (Continued)

Sample Number	Sample Description	Sample Location	Asbestos Content
8A	Plaster Ceiling Skim Coat	Storage Room	None Detected
8B	Plaster Ceiling Skim Coat	Receiving Storage Room	None Detected
8C	Plaster Ceiling Skim Coat	Room 146	None Detected
8D	Plaster Ceiling Skim Coat	Room 6	None Detected
8E	Plaster Ceiling Skim Coat	Room 119	None Detected
8F	Plaster Ceiling Skim Coat	Room 13	None Detected
8G	Plaster Ceiling Skim Coat	Room 15	None Detected
9A	12" Lime Green Floor Tile	Receiving Room	None Detected
9B	12" Lime Green Floor Tile	Receiving Room	None Detected
9C	12" Lime Green Floor Tile	Receiving Room	None Detected
10A	12" Lime Green Floor Tile Mastic	Receiving Room	None Detected
10B	12" Lime Green Floor Tile Mastic	Receiving Room	None Detected
10C	12" Lime Green Floor Tile Mastic	Receiving Room	None Detected
11A	3' x 4' Cementitious Panel on Cooler	Kitchen	None Detected
11B	3' x 4' Cementitious Panel on Cooler	Kitchen	None Detected
12A	Corkboard Adhesive on Cooler	Kitchen	12 % Chrysotile
12B	Corkboard Adhesive on Cooler	Kitchen	Positive Stop
13A	12" Tan Floor Tile	Kitchen	None Detected
13B	12" Tan Floor Tile	Kitchen	None Detected
14A	12" Tan Floor Tile Mastic	Kitchen	None Detected
14B	12" Tan Floor Tile Mastic	Kitchen	None Detected
15A	Air-Cell Pipe Insulation	Kitchen Office	30 % Chrysotile
15B	Air-Cell Pipe Insulation	Room 146	Positive Stop
15C	Air-Cell Pipe Insulation	Room 146	Positive Stop
16A	1' x 1' Perforated Wall Tile	Room 12	None Detected
16B	1' x 1' Perforated Wall Tile	Conference Room	None Detected
16C	1' x 1' Perforated Wall Tile	Conference Room	None Detected
17A	Glue Daubs on 1' x 1' Perforated Wall Tile	Room 12	None Detected
17B	Glue Daubs on 1' x 1' Perforated Wall Tile	Conference Room	None Detected
17C	Glue Daubs on 1' x 1' Perforated Wall Tile	Conference Room	None Detected
18A	4" Brown Covebase	Room 12	None Detected
18B	4" Brown Covebase	Room 15	None Detected
18C	4" Brown Covebase	Room 5	None Detected
19A	4" Brown Covebase Adhesive	Room 12	None Detected
19B	4" Brown Covebase Adhesive	Room 15	None Detected
19C	4" Brown Covebase Adhesive	Room 5	None Detected
20A	9" Tan Floor Tile	Room 12	10 % Chrysotile
20B	9" Tan Floor Tile	Room 10	Positive Stop
20C	9" Tan Floor Tile	Room 6	Positive Stop

**Wampanatuck Elementary School
 August 2013 Sample Locations and Results
 Table I (Continued)**

Sample Number	Sample Description	Sample Location	Asbestos Content
21A	9" Tan Floor Tile Mastic	Room 12	None Detected
21B	9" Tan Floor Tile Mastic	Room 10	None Detected
21C	9" Tan Floor Tile Mastic	Room 6	None Detected
22A	12" White Floor Tile	Cafeteria	None Detected
22B	12" White Floor Tile	Cafeteria	None Detected
22C	12" White Floor Tile	Cafeteria	None Detected
23A	12" White Floor Tile Mastic	Cafeteria	None Detected
23B	12" White Floor Tile Mastic	Cafeteria	None Detected
23C	12" White Floor Tile Mastic	Cafeteria	None Detected
24A	2' x 2' Flat Ceiling Tile	Cafeteria	None Detected
24B	2' x 2' Flat Ceiling Tile	Cafeteria	None Detected
24C	2' x 2' Flat Ceiling Tile	Room 161	None Detected
25A	2' x 4' Tectum Wall Tile	Cafeteria	None Detected
25B	2' x 4' Tectum Wall Tile	Cafeteria	None Detected
25C	2' x 4' Tectum Wall Tile	South Playroom	None Detected
26A	Stage Curtain	Cafeteria	None Detected
26B	Stage Curtain	Cafeteria	None Detected
27A	White Sink Basin Coating	Teachers Room	None Detected
27B	White Sink Basin Coating	Teachers Room	None Detected
21A	9" Tan Floor Tile Mastic	Room 12	None Detected
21B	9" Tan Floor Tile Mastic	Room 10	None Detected
21C	9" Tan Floor Tile Mastic	Room 6	None Detected
22A	12" White Floor Tile	Cafeteria	None Detected
22B	12" White Floor Tile	Cafeteria	None Detected
22C	12" White Floor Tile	Cafeteria	None Detected
23A	12" White Floor Tile Mastic	Cafeteria	None Detected
23B	12" White Floor Tile Mastic	Cafeteria	None Detected
23C	12" White Floor Tile Mastic	Cafeteria	None Detected
24A	2' x 2' Flat Ceiling Tile	Cafeteria	None Detected
24B	2' x 2' Flat Ceiling Tile	Cafeteria	None Detected
24C	2' x 2' Flat Ceiling Tile	Room 161	None Detected
25A	2' x 4' Tectum Wall Tile	Cafeteria	None Detected
25B	2' x 4' Tectum Wall Tile	Cafeteria	None Detected
25C	2' x 4' Tectum Wall Tile	South Playroom	None Detected
26A	Stage Curtain	Cafeteria	None Detected
26B	Stage Curtain	Cafeteria	None Detected
27A	White Sink Basin Coating	Teachers Room	None Detected
27B	White Sink Basin Coating	Teachers Room	None Detected

**Wampanatuck Elementary School
 August 2013 Sample Locations and Results
 Table I (Continued)**

Sample Number	Sample Description	Sample Location	Asbestos Content
28A	Interior Window Glazing	Hall by Conference Room	2 % Chrysotile
28B	Interior Window Glazing	Hall by Conference Room	Positive Stop
28C	Interior Window Glazing	Hall by Conference Room	Positive Stop
29A	9" Green Floor Tile	Room 117	10 % Chrysotile
29B	9" Green Floor Tile	Hall by Room 117	Positive Stop
30A	9" Green Floor Tile Mastic	Room 117	None Detected
30B	9" Green Floor Tile Mastic	Hall by Room 117	None Detected
31A	Gypsum Wallboard	Room 117	None Detected
31B	Gypsum Wallboard	Hall by Room 8	None Detected
31C	Gypsum Wallboard	Hall by Room 117	None Detected
32A	Joint Compound	Room 117	2 % Chrysotile
32B	Joint Compound	Hall by Room 8	Positive Stop
32C	Joint Compound	Hall by Room 117	Positive Stop
33A	12" Gray Floor Tile	Office	None Detected
33B	12" Gray Floor Tile	Office	None Detected
33C	12" Gray Floor Tile	Office	None Detected
34A	12" Gray Floor Tile Mastic	Office	None Detected
34B	12" Gray Floor Tile Mastic	Office	None Detected
35A	Perforated Acoustical Wall Tiles	Room 16	None Detected
35B	Perforated Acoustical Wall Tiles	Room 16	None Detected
35C	Perforated Acoustical Wall Tiles	Room 16	None Detected
36A	1/4" Covering on Bath Duct	Room 16	14 % Chrysotile
36B	1/4" Covering on Bath Duct	Room 16	Positive Stop
36C	1/4" Covering on Bath Duct	Room 16	Positive Stop
37A	12" Tan Marble Floor Tile	Room 161	12 % Chrysotile
37B	12" Tan Marble Floor Tile	Room 161	Positive Stop
37C	12" Tan Marble Floor Tile	Room 161	Positive Stop
38A	12" Tan Marble Floor Tile Mastic	Room 161	12 % Chrysotile
38B	12" Tan Marble Floor Tile Mastic	Room 161	Positive Stop
38C	12" Tan Marble Floor Tile Mastic	Room 161	Positive Stop
39A	Canvas on Fiberglass Pipe	Room 161	None Detected
39B	Canvas on Fiberglass Pipe	Room 161	None Detected
39C	Canvas on Fiberglass Pipe	Room 161	None Detected
40A	Pipe Fitting Insulation	Room 161	14 % Chrysotile
40B	Pipe Fitting Insulation	Room 161	Positive Stop
40C	Pipe Fitting Insulation	Room 17	Positive Stop
40D	Pipe Fitting Insulation	Boys Room E	Positive Stop
40E	Pipe Fitting Insulation	Girls Room E	Positive Stop
40F	Pipe Fitting Insulation	Room 21	Positive Stop
40G	Pipe Fitting Insulation	Room 18	Positive Stop

**Wampatuck Elementary School
 August 2013 Sample Locations and Results
 Table I (Continued)**

Sample Number	Sample Description	Sample Location	Asbestos Content
41A	Mosaic Sheet Flooring	Room 17	20 % Chrysotile
41B	Mosaic Sheet Flooring	Room 17	Positive Stop
41C	Mosaic Sheet Flooring	Room 17	Positive Stop
42A	Mosaic Sheet Flooring Adhesive	Room 17	None Detected
42B	Mosaic Sheet Flooring Adhesive	Room 17	None Detected
42C	Mosaic Sheet Flooring Adhesive	Room 17	None Detected
43A	Compressed Wall Board Panels	Room 17	None Detected
43B	Compressed Wall Board Panels	Room 17	None Detected
43C	Compressed Wall Board Panels	Room 17	None Detected
44A	2' x 2 Fissured Ceiling Tile	East Wing	None Detected
44B	2' x 2 Fissured Ceiling Tile	East Wing, Girls Room	None Detected
44C	2' x 2 Fissured Ceiling Tile	East Wing, Boys Room	None Detected
45A	Black Sink Undercoating	Room 26	5 % Chrysotile
45B	Black Sink Undercoating	Room 25	Positive Stop
45C	Black Sink Undercoating	Room 24	Positive Stop
46A	Interior Window Glazing at Hall Doors	Hall at Room 24	3 % Chrysotile
46B	Interior Window Glazing at Hall Doors	Hall at Room 24	Positive Stop
46C	Interior Window Glazing at Hall Doors	Hall at Room 24	Positive Stop
47A	Cementitious Panel Above Door	Cafeteria	30 % Chrysotile
47B	Cementitious Panel Above Door	N. Playroom	Positive Stop
47C	Cementitious Panel Above Door	N. Playroom	Positive Stop

Bold indicates bulk sample analyzed positive for Asbestos (>1% asbestos containing)

Positive Stop indicates representative bulk sample analyzed positive for Asbestos.

Section 1
Inspection Report (continued)

The following is a list of materials that were determined or assumed to be asbestos-containing:

Pipe Insulation	Pipe Fitting Insulation
9" Tan Floor Tile	9" Green Floor Tile
9" Brown Floor Tile	Cementitious Panel Above Doors
12" Tan Marble Floor Tile	12" Tan Marble Floor Tile Mastic (Black)
12" Off-White Gray Spec Floor Tile	12" Off-White Gray Spec FT Mastic
Mosaic Sheet Flooring	Black Sink Undercoating
Interior Window Glazing	Joint Compound

The following is a list of materials that were found and determined to be non-asbestos:

12" Multi-Color Floor Tile	12" Multi-Color Floor Tile Mastic
12" Lime Green Floor Tile	12" Lime Green Floor Tile Mastic
12" Tan Floor Tile	12" Tan Floor Tile Mastic
12" White Floor Tile	12" White Floor Tile Mastic
12" Gray Floor Tile	12" Gray Floor Tile Mastic
9" Brown Floor Tile Mastic (Black)	9" Tan Floor Tile Mastic (Black)
9" Green Floor Tile Mastic (Black)	Mosaic Sheet Flooring Adhesive
4" Brown Covebase	4" Brown Covebase Adhesive
Plaster Ceiling Base Coat	Plaster Ceiling Skim Coat
3' x 4' Cementitious Panel on Cooler	2' x 4' Tectum Wall Tile
1' x 1' Perforated Wall Tile	Glue Daubs on 1' x 1' Wall Tile
2' x 2' Flat Ceiling Tile	Perforated Acoustical Wall Tiles
2' x 2' Fissured Ceiling Tile	Compressed Wall Board Panels
Stage Curtain	White Sink Basin Coating
Gypsum Wallboard	Canvas on Fiberglass Pipe

VERTEX recommends an ACMs Survey be conducted prior to any renovation activities to comply with the EPA Title 40 CFR Part 61, NESHAPs and the Massachusetts Department of Environmental Protection Regulations.

Section 1
Inspection Report (continued)
Hazard Assessment

Each ACM homogeneous area is assessed to determine the asbestos hazard. Factors considered when assessing homogeneous area hazard include: the friability of the material, the condition of material including type, severity, and extent of damage, the material's potential for disturbance (including accessibility and air flow) and the material's potential for damage. From this classification, a decision tree is used to determine the appropriate response action sufficient to protect human health and environment.

The location, estimated quantities, condition and Homogenous Area Hazard Assessment Category for the identified ACMs are presented in Appendix A. The following is homogenous area assessment for each ACM identified.

Homogeneous Area Assessment

Homogeneous Area #1-Pipe Insulation

Classification: Friable Thermal System Insulation

Asbestos-containing Pipe Insulation is generally located throughout the school above drop ceilings and assumed above hard ceilings and/or behind walls. Please refer to Appendix A which includes the locations, conditions, and estimated quantities. The pipe insulation where accessible was observed in generally good condition, friable and presents a potential for damage. In addition, the Designated Person should assume that potential asbestos-containing pipe insulation may be located behind walls and ceilings not accessible.

Homogeneous Area #2-Pipe Fitting Insulation

Classification: Friable Thermal System Insulation

Asbestos-containing Pipe Fitting Insulation is generally located throughout the school above drop ceilings and assumed above hard ceilings and/or behind walls. Please refer to Appendix A which includes the locations, conditions, and estimated quantities. The pipe fitting insulation where accessible was observed in generally good condition, friable and presents a potential for damage except for displayed damage observed within the Kitchen Office. In addition, the Designated Person should assume that potential asbestos-containing pipe fitting insulation may be located behind walls and ceilings not accessible.

Homogeneous Area #3- 9"x 9" Tan Floor Tile

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing 9" x 9" Tan Floor Tile is generally located within the original section at the school. Please refer to Appendix A for the locations and estimated quantities. The 9" Tan Floor Tile generally is covered by 12" Tan Floor Tile, non-friable and presents a potential for damage.

Section 1
Inspection Report (continued)
Hazard Assessment

Homogeneous Area #4- 9"x 9" Brown Floor Tile

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing 9" x 9" Brown Floor Tile is generally located within the original section at the school. Please refer to Appendix A for the locations, estimated quantities and conditions. The 9" Brown Floor Tile generally displays minor damage in several areas, non-friable and presents a potential for damage.

Homogeneous Area #5- 9"x 9" Green Floor Tile

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing 9" x 9" Green Floor Tile is located within the North Hallway and Room 117 at the school. The 9" Green Floor Tile is in generally good condition, non-friable and presents a potential for damage.

Homogeneous Area #6 12" x 12" Tan/Marble Floor Tile

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing 12" x 12" Tan/Marble Floor Tile is generally located within the addition section at the school. The 12" Tan/Marble Tile is now covered by 12" Tan Floor Tile reportedly conducted between July and August 2023. Please refer to Appendix A for the locations, estimated quantities and conditions. The 12" Tan/Marble Floor Tile displays significant damage in Room 220-Custodial Closet.

Homogeneous Area #7 12" x 12" Off-White Gray Spec Floor Tile

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing 12" x 12" Off-White Gray Spec Floor Tile is within the Rooms 222 and 224 as well as the Speech Room at the school. The 12" x 12" Off-White Gray Spec Floor Tile is in generally good condition, non-friable and presents a potential for damage.

Homogeneous Area #8 Black Floor Tile Mastic

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing Black Floor Tile Mastic is generally located within the addition section at the school. The Black Floor Tile Mastic is covered and associated with 12" x 12" Off-White Gray Spec Floor Tile and 12" Tan/Marble Floor Tile.

Section 1
Inspection Report (continued)
Hazard Assessment

Homogeneous Area #9 Mosaic Sheet Flooring

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing Mosaic Sheet Flooring is within the Room 17 at the school. The Mosaic Sheet Flooring is in generally good condition, non-friable and presents a potential for damage.

Homogeneous Area #10-Interior Window Glazing

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing Interior Window Glazing is located on the Interior Partition Windows above the doorways the Boys and Girls Rooms (110 and 113) as well as the Conference Room (119) at the school. The Interior Window Glazing was observed in generally good condition, non-friable and presents a potential for damage.

Homogeneous Area #11- Cementitious Panels Above Doors

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing Panels Above Doors are generally located at the entry ways to classrooms within the original section of the school. Please refer to Appendix A for the locations, estimated quantities and conditions. The Panels Above Doors were observed in generally good condition, non-friable and presents a potential for damage.

Homogeneous Area #12- Joint Compound

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing Joint Compound is located on the Gypsum Wallboard with the North Hallway and Room 117. The Joint Compound was observed in generally good condition, non-friable and presents a potential for damage.

Homogeneous Area #13 Black Sink Mastic

Classification: Non-Friable Miscellaneous ACM

Asbestos-containing Black Sink Mastic is generally located under the sink areas within the addition section classrooms at the school. Please refer to Appendix A for the locations, estimated quantities and conditions. The Black Sink Mastic is in generally good condition, non-friable and presents a potential for damage.

SECTION 2

RESPONSE ACTION DETERMINATION

Section 2

Response Action Determination

The following is based on the Decision Tree for Thermal System Insulation Type ACM. The recommended response actions are determined utilizing the “decision tree” approach for Response Action Determination as outlined in EPA’s “Asbestos Hazard Emergency Response Act,” (AHERA) 40 CFR 763. Because of defined friability factors associated with surfacing and miscellaneous materials versus thermal system insulation, separate decision trees are utilized for each group of materials.

Decision Trees are used to estimate the risk associated with exposure to asbestos in a given homogeneous area, and to recommend certain response actions, which are consistent with regulatory requirements. Eight response actions are recommended for both thermal system insulation and for surfacing/miscellaneous insulation. The response section number given to each homogeneous area indicates a priority for action, the lower the number, the more serious the hazard. Most response actions call for an operations and maintenance program, assuming that this is the least burdensome method which still protects human health and environment. This does not prohibit the building owner from removal of ACM at any time, if that is the preferred response action.

Recommended response actions are based upon the material condition, disturbance, air-flow and the potential for damage. Potential response actions include the following:

1. Significantly Damaged Thermal System Insulation: **Response Action 1.** Isolate the area and restrict access to the area. ACM should be removed as soon as possible.
2. Damaged Thermal System Insulation with High Disturbance: **Response Action 2.** Continue O&M program and remove the ACM as soon as possible or reduce the potential for disturbance.
3. Damaged Thermal System Insulation with Moderate Disturbance and in the Presence of an Air Stream: **Response Action 2.** Continue with O&M Program and remove the ACM as soon as possible or reduce the potential for disturbance.
4. Damaged Thermal System Insulation with Moderate Disturbance: **Response Action 3.** Repair ACM, continue with O&M Program.
5. Damaged Thermal System Insulation with Low Disturbance and in the Presence of an Air Stream: **Response Action 4.** Repair ACM, continue with O&M Program.
6. Damaged Thermal System Insulation with Low Disturbance: **Response Action 5.** Repair ACM, continue with O&M Program.
7. Undamaged Thermal System Insulation with High Disturbance: **Response Action 6.** Continue with O&M Program and take preventative measures to reduce disturbance.
8. Undamaged Thermal System Insulation with Moderate Disturbance: **Response Action 7.** Continue with O&M Program and take preventative measure to reduce disturbance.
9. Undamaged Thermal System Insulation with Low Disturbance: **Response Action 7.** Continue with O&M Program and take preventative measure to reduce disturbance.

Section 2 Response Action Determination

The following is based on the Decision Tree for Surfacing and Miscellaneous ACM. Recommended response actions are based upon friability, material condition, disturbance, air flow and the potential for damage. Potential response actions include the following:

1. Friable Surfacing or Miscellaneous ACM with Significant Damage: **Response Action 1:** Isolate the area and restrict access to the area. Remove the ACM as soon as possible.
2. Friable Surfacing or Miscellaneous ACM with Damage and a High Disturbance: **Response Action 2:** Continue with O&M Program and remove ACM as soon as possible or reduce the potential for disturbance.
3. Friable Surfacing or Miscellaneous ACM with Damage, Moderate Disturbance and in the Presence of an Air Stream: **Response Action 2:** Continue with O&M Program and remove ACM as soon as possible or reduce the potential for disturbance.
4. Friable Surfacing or Miscellaneous ACM with Damage and Moderate Disturbance: **Response Action 3:** Continue with O&M Program and schedule removal when practical and cost-effective
5. Friable Surfacing or Miscellaneous ACM with Damage, Low Disturbance and in the Presence of an Air Stream: **Response Action 4:** Continue with O&M Program and schedule removal when practical and cost-effective
6. Friable Surfacing or Miscellaneous ACM with Damage and Low Disturbance: **Response Action 5.** Continue with O&M Program and schedule removal when practical and cost-effective
7. Friable Surfacing or Miscellaneous ACM with No Damage and High Disturbance: **Response Action 6.** Take preventative measures to reduce the disturbance.
8. Friable Surfacing or Miscellaneous ACM with No Damage and Moderate Disturbance: **Response Action 7.** Take preventative measure to reduce the disturbance.
9. Friable Surfacing or Miscellaneous ACM with No Damage and Low Disturbance: **Response Action 8.** Take preventative measure to reduce the disturbance.
10. Non-Friable Surfacing or Miscellaneous ACM: **Response Action 8:** Continue with O&M until major renovation or demolition requires removal under the EPA NESHAPS, or until hazard assessment factors change.

Section 2
Response Action Determination (continued)

Advantages and Disadvantage to Abatement Alternatives

The decision trees outlined in AHERA 40 CFR 763 are used to provide the “best” alternative for the specific conditions in each homogeneous area.

Below is a discussion of the alternative approaches to asbestos management in a building.

Long Term Operation & Maintenance Program

Advantages:

- *Low initial cost for implementation
- *Good interim plan
- *An O&M program may be implemented and carried out by in house trained personnel.

Disadvantages:

- *Asbestos remains in the building
- *Condition of the asbestos must be monitored
- *Cost of training and special work procedures may be significant
- *Effectiveness may be limited where control of the building occupants is difficult

Encapsulation

Advantages:

- *Reduces the risk of release of asbestos fibers
- *Initial cost is lower than the cost of asbestos removal
- *Asbestos-containing material may still serve its initial purpose
- *Quick temporary means of repair

Disadvantages:

- *Asbestos remains in the building and encapsulant makes removal more difficult
- *Improper encapsulation may cause the material to delaminate or pull away from substrate
- *Asbestos-containing material must have an O&M program
- *Similar preparation for asbestos removal is required for encapsulation
- *Long term cost may be greater than asbestos removal is periodic reapplication of the encapsulant is required

Section 2
Response Action Determination (continued)

Enclosure

Advantages:

- *Enclosure reduces immediate exposure
- *Initial cost of enclosure is lower than the cost of asbestos removal
- *Asbestos-containing material may still serve its initial purpose
- *Quick temporary means of repair

Disadvantages:

- *Asbestos remains in place and later removal is more difficult
- *If maintenance is required of the systems insulated with asbestos, the asbestos will be exposed
- *An O&M program will have to be implemented for the asbestos-containing material
- *Similar preparation for asbestos removal is required for enclosure

Removal

Advantages

- *Asbestos-containing material is eliminated from the building
- *There is no need for an O&M plan
- *Initial cost is great, but the future costs are eliminated

Disadvantages:

- *Re-insulating, re-fireproofing, or replacement of materials may be required
- *Improper removal may raise levels of airborne fibers higher than background levels
- *The initial cost of removal is very high
- *Areas of the building involved in asbestos removal may not be occupied during removal

SECTION 3

UPDATED RECOMMENDED RESPONSE ACTIONS

Section 3

Recommended Response Actions

The recommended response actions are for all the homogenous areas found within the school. The response actions are determined utilizing the decision tree approach for Response Action Determination as described in Section 2.

Homogeneous Area #1-Pipe Insulation

Response Action 7: The pipe insulation located at the school is in generally good condition. Limit the potential for disturbance and continue the Operations and Maintenance (O&M) Program until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change. It should be noted that asbestos-containing pipe insulation may be located above hard ceilings and/or behind walls. As such, a thorough exploratory inspection should be conducted prior to any renovations that may impact wall or ceiling areas.

Homogeneous Area #2-Pipe Fitting Insulation

Response Action 3: The pipe fitting insulation identified within the Kitchen Office displayed minor damage. Retain an Asbestos Project Designer to prepare a Work Plan for the repair or remove the damaged pipe fitting insulation and retain a Massachusetts certified Abatement Contractor to complete the response action following the Work Plan. Recommended completion date of the work activities: August 2024.

Response Action 7: The remaining pipe fitting insulation located at the school is in generally good condition. Limit the potential for disturbance and continue the O&M Program until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change. It should be noted that asbestos-containing pipe fitting insulation may be located above hard ceilings and/or behind walls. As such, a thorough exploratory inspection should be conducted prior to any renovations that may impact wall or ceiling areas.

Homogeneous Area #3- 9"x 9" Tan Floor Tile

Response Action 8: The 9" x 9" Tan Floor Tile located at the school is in generally covered by 12" Tan Floor Tile. Please refer to Appendix A which includes the locations and estimated quantities of the 9" x 9" Tan Floor Tile. Continue the O&M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Section 3
Recommended Response Actions (Continued)

Homogeneous Area #4- 9"x 9" Brown Floor Tile

Response Action 8: The 9" x 9" Brown Floor Tile located at the school is in generally good condition or covered. Please refer to Appendix A which includes the locations and estimated quantities of the 9" x 9" Brown Floor Tile. Continue the O& M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Homogeneous Area #5- 9"x 9" Green Floor Tile

Response Action 8: The 9" x 9" Green Floor Tile located within the North Hallway and Room 117 is in generally good condition or covered. Continue the O& M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Homogeneous Area #6 12" x 12" Tan/Marble Floor Tile

Response Action 8: The 12" x 12" Tan/Marble Floor Tile identified within 220-Custodial displayed significant damage. Retain an Asbestos Project Designer to prepare a Work Plan for the removal and replacement of the damaged floor tile and retain a Massachusetts certified Abatement Contractor to complete the response action following the Work Plan. Recommended completion date of the work activities: July 2021.

Response Action 8: The remaining 12" x 12" Tan/Marble Floor Tile located at the school is in generally covered by 12" Tan Floor Tile. Please refer to Appendix A which includes the locations and estimated quantities of the 12" x 12" Tan/Marble Floor Tile. Continue the O& M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Homogeneous Area #7 12" x 12" Off-White Gray Spec Floor Tile

Response Action 8: The 12" x 12" Off-White Gray Spec Floor Tile within Rooms 222 and 224 as well as the Speech Room is covered by 12" Tan FloorTile. Continue the O& M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Section 3
Recommended Response Actions (Continued)

Homogeneous Area #8 Black Floor Tile Mastic

Response Action 8: The Black Floor Tile Mastic is covered and associated with 12" x 12" Off-White Gray Spec Floor Tile and 12" Tan/Marble Floor Tile. Continue the O& M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Homogeneous Area #9 Mosaic Sheet Flooring

Response Action 8: The Mosaic Sheet Flooring is within the Room 17 is in generally good condition. Continue the O& M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Homogeneous Area #10-Interior Window Glazing

Response Action 8: The Interior Window Glazing located on the Interior Partition Windows above the doorways the Boys and Girls Rooms (110 and 113) as well as the Conference Room (119) is in generally good condition. Continue the O& M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Homogeneous Area #11- Cementitious Panels Above Doors

Response Action 8: The Panels Above Doors located at the entry ways to classrooms within the original section of the school are in generally good condition. Continue the O& M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Homogeneous Area #12- Joint Compound

Response Action 8: The Interior Window Glazing on the Gypsum Wallboard with the North Hallway and Room 117 is in generally good condition. Continue the O& M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

Homogeneous Area #13 Black Sink Mastic

Response Action 8: The Black Sink Mastic is generally located under the sink areas within the addition section classrooms at the school is in generally good condition. Continue the O& M Program and manage the material in place until major renovations or demolition requires the removal of this material, or until the hazard assessment factors change.

SECTION 4

RECORDKEEPING REQUIREMENTS AND RECOMMENDATIONS

Section 4

Recordkeeping Requirements and Recommendations

The AHERA regulations have very specific requirements for the maintenance of records associated with the management of the identified ACMs in the school. The following is a list of some of the key items that the LEA Designated Person must maintain as part of the package:

- Initial AHERA inspection report and Asbestos Management Plan
- Subsequent 3-year reinspection reports.
- 6-month surveillance reports.
- Documentation for minor and major fiber release episodes. This includes abatement work performed by outside contractors as well as work performed by 16 hour trained maintenance personnel no matter how small.
- Documentation for completion of response actions (i.e. clearance testing, waste shipment records, etc.). This should always include applicable training and certification documentation for the parties involved performing the work activities.
- Labeling of ACM (friable)
- Yearly notice to parents, teachers and staff.
- Training and medical exams for 16-hour trained personnel. Although training does not require renewal. Medicals are to be performed every year. In addition, 16-hour personnel should be fit tested every six months.
- Two-hour awareness training for staff. Any new workers are required to receive this training at start of employment. Training should include specific review of ACMs in the building they are working in.

The above items are some of the key items, which need to be incorporated into the plan. The following are some recommendations on how best to maintain for easy access and review by outside parties:

- Maintain an updated three-ring binder for the school. Have a duplicated copy, one for administration office and one for the facilities office.
- Create tab sections in the binder. Each section should contain the information above. This will allow for easy review and update.
- Ensure that for every major and minor fiber release episode, that all documentation is received.
- As you update your file, ensure the school's is updated.

Section 4

Recordkeeping Requirements and Recommendations (continued)

Also, it is also required that if outside contractors enter building perform work that they review areas where asbestos may be present that will be near their work. Have a log at the school for them to sign that they have read and understand. This will protect the school from liability and ensure outside contractors will not disturb asbestos. Finally, periodically review program internally and with your 16-hour persons to ensure compliance.

The pipe fitting insulation identified within the Kitchen Office displayed minor damage. Retain an Asbestos Project Designer to prepare a Work Plan for the repair or remove the damaged pipe fitting insulation and retain a Massachusetts certified Abatement Contractor to complete the response action following the Work Plan. Recommended completion date of the work activities: August 2024.

The 12" x 12" Tan/Marble Floor Tile identified within 220-Cusodial displayed significant damage. Retain an Asbestos Project Designer to prepare a Work Plan for the removal and replacement of the damaged floor tile and retain a Massachusetts certified Abatement Contractor to complete the response action following the Work Plan. Recommended completion date of the work activities: August 2024.

VERTEX recommends continuing the periodic cleaning schedule with properly trained staff (i.e. 2-Hour Asbestos Awareness) utilizing HEPA-vacuums and wet mopping.

A required six-month periodic surveillance inspection should be scheduled for November 2024.

VERTEX recommends an ACMs Survey be conducted prior to any renovation activities to comply with the EPA Title 40 CFR Part 61, NESHAPs and the Massachusetts Department of Environmental Protection Regulations as well as Transmission Electron Microscopy (TEM) confirmatory analysis for Non-Friable Organically Bound (NOB) Materials identified non-detected (i.e. mastics, adhesives, etc.) prior to disturbance.

SECTION 5

ESTIMATED RESOURCES REQUIRED TO COMPLETE THE RESPONSE ACTIONS

Section 5
Estimated Resources Required to Complete the Response Actions

This section contains the estimated resources required to complete the abatement activities of the identified damaged ACMs. These estimates will vary according to competitive bidding, accessibility, location, and condition of ACMs, phasing of work, etc. The cost estimate below does not include abatement contractor mobilization, abatement design and/or project monitoring services.

Estimated Cost to complete the Response Actions at the Wampatuck Elementary School in Scituate, Massachusetts:

\$1,100.00*

Cost Estimate Worksheet can be found in Appendix B.

* The estimated cost provided above is developed from current Abatement Contractor Unit pricing. These estimates will vary according to competitive bidding, accessibility, location, and condition of ACMs, phasing of work, etc. In addition, the costs above do not include mobilization of the Abatement Contractor, Abatement Work Plan/Design, Project Monitoring and/or Clearance Testing Services for the completion of the response actions. Please refer for below unit pricing regarding costs for the Contractor Mobilization and Clearance Testing Services:

Abatement Work Plan/Design Specification = \$500-\$2,500.00
Abatement Contactor Mobilization = \$1,500.00-\$2,500.00
Project Monitoring/Clearance Testing = \$520.00-\$760.00/per shift
Transmission Electron Microcopy (TEM) Analysis = \$75.00-\$100.00/sample
Phase Contrast Microscopy (PCM) Analysis = No Charge -\$15.00/sample
Clearance Report Preparation = \$350.00-\$800.00

**The estimated cost provided above does not include costs that may be associated with two-hour asbestos awareness training, OSHA 16-hr Operations and Maintenance Training, and/or the labor to conduct the required six-month surveillance re-inspections. Please refer below for estimated costs that may be associated with the mentioned above:

2-Hour Asbestos Awareness Training = \$75/person
OSHA 16-hr Operations and Maintenance Training = \$300/person
Six-Month Periodic Surveillance Inspection = \$400/inspection

SECTION 6

ESTIMATED RESOURCES REQUIRED FOR THE ABATEMENT OF THE IDENTIFIED ACBMs

Section 6
Estimated Resources Required For Abatement of the Identified ACMs

This section contains the estimated resources required to perform the removal of identified ACMs, however EPA recommends the ACMs to be managed in place if they are not damaged. Alternative abatement costs are estimated using current Abatement Contractor Estimates. These estimates will vary per competitive bidding, accessibility, location, and condition of ACMs, phasing of work, etc. The cost estimate below is a worst-case scenario if all identified ACMs were to be removed. The cost estimate below does not include abatement contractor mobilization, abatement design and/or project monitoring services.

Estimated Cost for the Removal of ACMs from the Wampatuck Elementary School in Scituate, Massachusetts: \$350,000.00*

Cost Estimate Worksheet can be found in Appendix C.

*The estimated cost above does not include removal of potentially concealed ACMs within the interior of the school. In addition, the estimated cost provided above does not include abatement of potential ACMs on the exterior of the site building and/or beyond the AHERA inspection.

** The estimated cost provided above is developed from current Abatement Contractor Unit pricing. These estimates will vary according to competitive bidding, accessibility, location, and condition of ACMs, phasing of work, etc. In addition, the costs above do not include mobilization of the Abatement Contractor, Abatement Work Plan/Design, Project Monitoring and/or Clearance Testing Services for the completion of the response actions. Please refer for below unit pricing regarding costs for the Contractor Mobilization and Clearance Testing Services:

Abatement Work Plan/Design Specification = \$500-\$2,500.00
Abatement Contactor Mobilization = \$1,500.00-\$2,500.00
Project Monitoring/Clearance Testing = \$520.00-\$760.00/per shift
Transmission Electron Microcopy (TEM) Analysis = \$75.00-\$100.00/sample
Phase Contrast Microscopy (PCM) Analysis = No Charge -\$15.00/sample
Clearance Report Preparation = \$350.00-\$800.00

SECTION 7

OPERATIONS AND MAINTENANCE

Section 7
Operations and Maintenance Program

INTRODUCTION

The Scituate Public School District has established an overall asbestos control program that is designed to minimize exposure of all occupants of the school to asbestos fibers located at the Wampatuck Elementary School. This Operations and Maintenance (O&M) Plan is an integral part of the overall program. It sets guidelines for the proper in-place management of all assumed and identified ACMs located in the building.

This O&M plan contains the following sections:

- A. A description of the **duties of the LEA Designated Person (DP)**.
- B. A procedure for **notifying** workers, tenants, and other visitors where ACM are located, and stressing the importance of avoiding disturbing the ACM in any way.
- C. The detailed description of **O&M Activities**, including:
 - 1. **Emergency procedures** for both major and minor episodes of fiber release;
 - 2. **Periodic surveillance** of ACM, so that any changes in the condition of ACM can be noted, assessed, and documented; and
 - 3. Detailed descriptions of **work procedures** for both general maintenance and Asbestos Associated Project Workers, which must be used so that workers can avoid or minimize fiber release when performing activities that may disturb ACM.
- D. A list of **records** that must be kept to document O&M and abatement activities.
- E. **Training requirements** for the DP, and custodial and maintenance staff.

In general, asbestos represents a health hazard **only** if fibers are breathed into the lungs or, in rare cases, are swallowed. Asbestos-containing materials that are non-friable (i.e. cannot be easily broken or crumbled by hand pressure) are not hazardous as long as they are intact and in good condition. Because friable materials can be easily crumbled or crushed, they are more susceptible to airborne fiber release than are non-friable materials.

It is a policy of the Scituate Public School District that untrained employees and outside contractors **DO NOT** handle, touch or otherwise disturb any material that is asbestos or suspected of containing asbestos. A properly qualified and trained individual must handle any material that is, or may contain asbestos. Non-asbestos materials have been and may be identified by the asbestos coordinator using one or more of the following criteria: (1) lab analysis, (2) results of previous lab analysis, (3) product composition labels, (4) receipts, and so forth. At no time will any employee, student, or outside contractor assume a material to be asbestos-free. An inventory of ACMs identified from the inspection are presented in Appendix A.

Section 7



Operations and Maintenance Program (Continued)

1. DUTIES OF THE ASBESTOS MANAGEMENT PLAN DESIGNATED PERSON

The DP oversees the implementation and management of the O&M plan. Duties of the DP include (1) notifying building staff, workers, and outside contractors where ACM is located in the building, (2) assigning workers to tasks involving work that may disturb ACM, (3) ensuring that abatement and O&M activities are conducted by trained qualified personnel, and (4) keeping records of all asbestos-related activities at the property.

The DP must receive training related to asbestos issues (see “Training Requirements” of this plan).

2. NOTIFICATION

The DP shall ensure that building workers, outside contractors, and tenants are notified of the location, quantity, and physical condition of identified and assumed ACM that they might disturb. Such notification shall be accomplished by written notice, by personal communication, by posting signs at entrances to mechanical areas, and/or by labeling ACM. By informing occupants of potential hazards in their vicinity, the notification reduces the possibility that occupants will accidentally disturb ACM. The notification must stress that persons who disturb ACM may accidentally release asbestos fibers into the air, and that therefore everyone must avoid disturbing ACM. This notification will assure compliance with Occupational Health and Safety Administration (OSHA) Regulation 29 CFR Part 1926.1101, which regulates asbestos exposure as it relates to construction work (including building maintenance) and with 29 CFR 1910.1001, which regulates asbestos exposure in general industry (including normal housekeeping).

If asbestos-related construction, abatement, or O&M activities is conducted, the DP shall also notify the following persons about the presence, location, and quantity of ACM:

- A. Employees of the building, such as maintenance and custodial personnel who will work in or adjacent to areas containing ACM:
- B. Staff who will occupy areas containing ACM.
- C. Prospective employers applying for or bidding for work if their employees will be expected to work in or adjacent to areas containing ACM.
- D. Multiple employers occupying a work-site in the building, any of whose employees will be performing work within or adjacent to areas containing ACM.

Section 7
Operations and Maintenance Program (Continued)

Before conducting any work in the building that has the potential to impact ACM, contractors will be required to sign the Contractor's Asbestos Notification and Acknowledgment Form. In addition, all contractors and contractor's employees who work on the site will be required to notify the DP of the presence, location, and quantity of newly discovered ACM within 24 hours (or sooner if ACM is disturbed) of the discovery. If any building materials are discovered, the asbestos content of which is unknown, the material shall be presumed to contain asbestos, until the results of sampling and analysis prove otherwise. Appropriate sampling of the material shall be conducted by a Massachusetts Department of Labor and Work Force Development Division of Labor Standards accredited asbestos inspector and analyzed at an appropriately licensed asbestos analytical laboratory.

The DP shall ensure that all required warning signs are posted during abatement and O&M activities during which the release of asbestos fibers into the air is possible. Warning signs shall demarcate all regulated areas and shall bear the following information:

DANGER
ASBESTOS
MAY CAUSE CANCER
CAUSES DAMAGE TO LUNGS
AUTHORIZED PERSONNEL ONLY
RESPIRATORS AND PROTECTIVE
CLOTHING ARE REQUIRED IN THIS AREA

Contractors and in-house personnel who remove ACM within the site shall label all waste containers that contain ACM waste in accordance with OSHA and EPA guidelines.

The Massachusetts Department of Environmental Protection (DEP) and the Massachusetts Division of Labor Standards (DLS) will be notified anytime work will impact any quantity of ACM at the school.

The DP shall ensure that all previously installed ACM that have been identified in the facility are labeled or identified by signs, as feasible. All ACM that are friable and accessible, such as TSI located in mechanical areas or below suspended ceilings, will be labeled. Labels shall be attached to or posted in areas where employees, residents, and outside contractors who are likely to be exposed will clearly notice (such as at the entrance to mechanical rooms).

The labels shall bear the following information:

DANGER
CONTAINS ASBESTOS FIBERS
MAY CAUSE CANCER
CAUSES DAMAGE TO LUNGS
DO NOT BREATHE DUST
AVOID CREATING DUST

Posted signs may be used in lieu of labels to indicate the type and location of each ACM.



Section 7
Operations and Maintenance Program (Continued)

3. OPERATIONS AND MAINTENANCE ACTIVITIES

Operations and maintenance activities include:

- Emergency procedures to be followed in the event of a major or minor episode of fiber release;
- Periodic surveillance of ACM within at the school building;
- Work procedures associated with planned maintenance activities that may disturb ACM. Only properly trained personnel under the control and direction of the DP shall conduct operations and maintenance activities.
- Periodic Cleaning Activities

A. Emergency Procedures for Fiber Release Episodes

Fiber release episodes are categorized as *major* (the falling or dislodging of more than 3 square feet or 3 linear feet of friable ACM), or *minor* (the falling or dislodging of fewer than 3 square feet or 3 linear feet of friable ACM)

PROCEDURE FOR MAJOR EPISODE

1. Restrict entry into the area.
2. Immediately contact the DP
3. Post sign to prevent anyone from entering the area except persons necessary to perform the response action.
4. Shut off or temporarily modify the air-handling system to prevent the fibers from being distributed to other areas in the building.
5. The DP shall contact an accredited designer of abatement to prepare an abatement plan that specifies the appropriate response actions.
6. The DP shall ensure that only a Massachusetts Certified Asbestos Abatement Contractor conducts the response actions.

Section 7
Operations and Maintenance Program (Continued)

PROCEDURE FOR MINOR EPISODE

1. Thoroughly saturate the debris using all wetting methods necessary.
2. Clean the area using wet wiping techniques followed by vacuuming with a specially equipped High Efficiency Particulate Air (HEPA) vacuum.
3. Place all debris and all contaminated cleaning supplies (mop heads, rags, etc.) into a leak tight container, such as a 6-mil thick polyethylene waste bag, and seal the container. Place the sealed container into a second 6-mil thick polyethylene bag. If labeled waste bags are not used, apply warning label to outside of each bag used.
4. Repair the area of damaged ACM, as follows:
 - a. Use materials such as asbestos-free spackling, plaster, cement, or insulation; or
 - b. Seal the area with latex paint or an encapsulate; or
 - c. Immediately implement other appropriate response action.

B. Periodic Surveillance

Periodic surveillance of all known and assumed ACM shall be conducted once every six months. The purpose of the regularly scheduled surveillance is to ensure that any ACM that are damaged or that have deteriorated are detected in a timely manner. The DP shall use the information from the periodic surveillance in conjunction with ongoing reports from the periodic surveillance in conjunction with ongoing reports from service workers of changes in the condition of the ACM to take corrective action.

The periodic surveillance consists of a visual inspection of all known and assumed ACM. Periodic surveillance shall also include a visual and physical evaluation of ACM in order to determine the degree of damage and to assess the likelihood of future fiber release. The area in the immediate vicinity shall also be examined for potential loose ACM debris. The DP shall record the cause of the damage.

Only persons who have received at least the minimum asbestos-awareness training (see "Training Requirements", of this plan) shall conduct the periodic surveillance. The results of the surveillance shall be recorded on the periodic surveillance inspection form.

Section 7
Operations and Maintenance Program (Continued)

C. Work Procedures for General Maintenance Personnel

The following work practices shall be prohibited in all circumstances:

- Drilling holes in ACM;
- Damaging ACM while moving furniture or other objects;
- Sweeping or dusting floors, ceilings, moldings, or other surfaces in asbestos-contaminated environments;
- Using an ordinary vacuum to clean up asbestos-containing or asbestos contaminated debris (only vacuums equipped with a HEPA filter should be used);
- Removing potentially contaminated ventilation system filters without thoroughly wetting them; and
- Shaking potentially contaminated ventilation system filters.

D. Periodic Cleaning

The following is a general outline to be utilized for the properly trained personnel to conduct the periodic cleaning activities:

- Utilization of disposable rags to wet wipe of all non-porous horizontal surfaces followed by the use of a HEPA-equipped vacuum. Dry sweeping and/or dusting is not permitted to be used to clean the surfaces.
- The collected debris within the lined HEPA-equipped vacuum and disposal rags should be properly disposed of in a labeled asbestos-waste bag accompanied by a Waste Shipment Record for future disposal at a permitted facility that accepts asbestos waste.
- Document the Name of the individual conducting the work activities, location date and time of cleaning for proper recordkeeping. These records should be included within the AMP for the school.

Floor Tile Maintenance

Pursuant to the Occupational Safety and Health Administration (OSHA) Asbestos Standard 29 CFR 1910.1001, properly trained staff (i.e. 2-Hour Asbestos Awareness) should adhere to the OSHA's guidance for care of asbestos-containing flooring materials outlined below:

- Do not sand asbestos-containing flooring material;
- Use only low-abrasion buffing pads;
- Operate buffers only at speeds lower than 300 rpm;
- Use wet methods;
- Document the Name of the individual conducting the work activities, location date and time of cleaning for proper recordkeeping. These records should be included within the AMP for the school.

Section 7
Operations and Maintenance Program (Continued)

4. RECORDKEEPING REQUIREMENTS

The building owner shall maintain the following documentation pertaining to ACM in the facility:

- All data that are relied upon to demonstrate that suspect ACM do not in fact contain asbestos.
- All data communicated and received that identify the locations and quantities of ACM.
- All records associated with abatement projects and O&M activities. These documents shall be maintained during the term of ownership. They shall then be transferred to successive owners, in accordance with OSHA Regulation 1926.1101 (n).
- If the owner's employees conduct activities that may potentially cause them to be exposed to asbestos fibers, the owner shall keep the following additional records:
 - All employee exposure-monitoring records pursuant to OSHA Regulation 1926.1101(f).
 - All information relative to medical surveillance of employees pursuant to OSHA Regulation 1926.1101(m). Medical surveillance shall be required only if:
 1. Employees are required to conduct tasks that would result in their exposure to airborne concentrations of asbestos above the OSHA permissible exposure limit (PEL); or
 2. If employees conduct asbestos abatement tasks for more than 30 days per year.
- The owner shall maintain all employee-training records for one year beyond the employee's last date of employment.

5. TRAINING REQUIREMENTS

The extent of asbestos training for facility employees depends on the type of asbestos-related activities they will conduct. For most employees who will require training, a two-hour awareness course will be sufficient but necessary. For employees who are involved in activities where exposure to airborne asbestos fibers is likely, a more comprehensive 16-hour training course is necessary.

Section 7
Operations and Maintenance Program (Continued)

AWARENESS TRAINING

The curriculum shall include instruction in the following:

- The location, quantity, and physical condition of all ACM located in the facility.
- Recognition of damage, deterioration, and delaminating of ACM.
- The health effects associated with asbestos exposure, including the relationship between smoking and asbestos in producing lung cancer.
- Procedures to be implemented in the event of a minor or major episode of fiber release.
- The requirements for posting signs and affixing labels, and the meaning of the required legends for such signs and labels.

COMPREHENSIVE WORKER TRAINING

The curriculum shall include instruction in the following:

- All awareness training information described above.
- The nature of operations that could result in exposure to asbestos, and the importance of necessary protective controls and of procedures for minimizing exposure, including:
 - engineering controls
 - work practices,
 - respirators,
 - housekeeping procedures,
 - hygiene facilities,
 - protective clothing,
 - decontamination procedures,
 - emergency procedures,
 - waste disposal procedures and any necessary instruction in the use of these controls and procedures.

Section 7

Operations and Maintenance Program (Continued)

- The purpose, proper use, fitting instructions, and limitations of respirators.
- Medical surveillance program requirements
- The contents of the OSHA standard (1926.1101) regarding asbestos in construction.
- Hands-on-training in the use of respiratory protection, other personal protection measures, and work practices.

Detailed procedures for conducting small-scale, short duration abatement activities, as defined in Appendix A to Subpart E to EPA Regulation 40 CFR Part 763.

APPENDIX A

**LOCATIONS OF THE ASBESTOS CONTAINING MATERIALS AND
UPDATED CONDITONS**

Appendix A AHERA Inspection May 2024 Locations of the Identified Asbestos-Containing Materials Wampatuck Elementary School-266 Tilden Road						
Location	ACM Description	Estimated Quantity	VERTEX 2021 Cond.	VERTEX 2024 Updated Cond.	Fri.	HA #
<i>First Floor</i>						
Room 1 (101)	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	890 ft ²	MD (2 ft ²)	C	N	5
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5
	Cementitious Panel Above Door	6 ft ²	G	G	N	5
Room 2 (105)	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	890 ft ²	MD (4 ft ²)	C	N	5
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5
	Cementitious Panel Above Door	6 ft ²	G	G	N	5
105B	9" x 9" Brown Floor Tile (Under 12" Tan Floor Tile)	48 ft ²	MD (4 ft ²)	C	N	5
Room 3 (102)	9" x 9" Tan Floor Tile	890 ft ²	G	G	N	5
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5
	Cementitious Panel Above Door	6 ft ²	G	G	N	5
102B	9" x 9" Brown Floor Tile (Under 12" Tan Floor Tile)	48 ft ²	MD (4 ft ²)	C	N	5
Room 4 (106)	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	890 ft ²	G	G	N	5
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5
	Cementitious Panel Above Door	6 ft ²	G	G	N	5

Appendix A AHERA Inspection May 2024 Locations of the Identified Asbestos-Containing Materials Wampatuck Elementary School-266 Tilden Road						
Location	ACM Description	Estimated Quantity	VERTEX 2021 Cond.	VERTEX 2024 Updated Cond.	Fri.	HA #
<i>First Floor (Continued)</i>						
Room 5 (103)	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	890 ft ²	MD (24 ft ²)	C	N	6
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5
	Cementitious Panel Above Door	6 ft ²	G	G	N	5
103B	9" x 9" Brown Floor Tile (Under 12" Tan Floor Tile)	48 ft ²	MD (4 ft ²)	C	N	6
Room 6 (107)	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	890 ft ²	G	C	N	5
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5
	Cementitious Panel Above Door	6 ft ²	G	G	N	5
107B	9" x 9" Brown Floor Tile (Under 12" Tan Floor Tile)	48 ft ²	MD (6 ft ²)	C	N	6
Room 7 (104)	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	890 ft ²	G	C	N	5
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5
	Cementitious Panel Above Door	6 ft ²	G	G	N	5
Room 8 (108)	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	890 ft ²	G	C	N	5
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5
	Cementitious Panel Above Door	6 ft ²	G	G	N	5
North Boys Room (110)	Interior Window Glazing	12 lf	G	G	N	5
North Girls Room (113)	Interior Window Glazing	12 lf	G	G	N	5
North Storage (115)	9" x 9" Brown Floor Tile	120 ft ²	G	G	N	5
116	9" x 9" Brown Floor Tile	264 ft ²	G	G	N	5

Appendix A AHERA Inspection May 2024 Locations of the Identified Asbestos-Containing Materials Wampanoag Elementary School-266 Tilden Road						
Location	ACM Description	Estimated Quantity	VERTEX 2021 Cond.	VERTEX 2024 Updated Cond.	Fri.	HA #
First Floor (Continued)						
114	9" x 9" Brown Floor Tile	72 ft ²	G	G	N	5
112	9" x 9" Brown Floor Tile	20 ft ²	G	G	N	5
111	9" x 9" Brown Floor Tile	20 ft ²	G	G	N	5
North Hallway	9" x 9" Green Floor Tile	476 ft ²	G	G	N	5
	Drywall/Joint Compound	720 ft ²	G	G	N	5
Room 117	9" x 9" Green Floor Tile (Under 12" Tan Floor Tile)	500 ft ²	G	C	N	5
	Drywall/Joint Compound	720 ft ²	G	G	N	5
Room 9 (133)	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	900 ft ²	MD (6 ft ²)	C	N	6
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5
138	9" x 9" Brown Floor Tile	40 ft ²	G	G	N	5
Room 10	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	900 ft ²	MD (28 ft ²)	C	N	6
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5
137	9" x 9" Brown Floor Tile	40 ft ²	G	G	N	5
Room 11	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	900 ft ²	MD (4 ft ²)	C	N	6
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5
Room 12 (143)	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	900 ft ²	G	G	N	5
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5



Appendix A AHERA Inspection May 2024 Locations of the Identified Asbestos-Containing Materials Wampatuck Elementary School-266 Tilden Road						
Location	ACM Description	Estimated Quantity	VERTEX 2021 Cond.	VERTEX 2024 Updated Cond.	Fri.	HA #
First Floor (Continued)						
146	9" x 9" Brown Floor Tile	168 ft ²	G	G	N	5
Kitchen	Corkboard and Adhesive	70 ft ²	C	C	N	5
Kitchen Office	Pipe Insulation	30 lf	G	G	Y	6
	Pipe Fitting Insulation	3 Units	MD (3)	MD (3)	Y	1
Cafetorium	12" x 12" White Floor Tile	3000 ft ²	G	G	N	5
	Black Floor Tile Mastic	3000 ft ²	C	C	N	5
	Cementitious Panel Above Doors	42 ft ²	G	G	N	5
Room 13 (165)	12" White Blue Spec Floor Tile	900 ft ²	G	G	N	5
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	900 ft ²	C	C	N	5
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5
Room 14 (164)	12" White Blue Spec Floor Tile	900 ft ²	G	G	N	5
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	900 ft ²	C	C	N	5
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5
Room 15 (163)	12" White Blue Spec Floor Tile	900 ft ²	G	G	N	5
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	900 ft ²	C	C	N	5
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5

Appendix A AHERA Inspection May 2024 Locations of the Identified Asbestos-Containing Materials Wampatuck Elementary School-266 Tilden Road						
Location	ACM Description	Estimated Quantity	VERTEX 2021 Cond.	VERTEX 2024 Updated Cond.	Fri.	HA #
First Floor (Continued)						
Room 16	12" White Blue Spec Floor Tile	900 ft ²	G	G	N	5
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	900 ft ²	C	C	N	5
	Pipe Insulation (Assumed Above Ceiling)	lf	U	U	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Chalkboard	88 ft ²	G	G	N	5
Room 16.1	12" White Blue Spec Floor Tile	64 ft ²	G	G	N	5
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	64 ft ²	C	C	N	5
	Pipe Insulation	20 lf	G	G	Y	6
	Pipe Fitting Insulation	3 Units	G	G	Y	6
Room 17 (162)	Mosaic Pattern Sheet Flooring	1156 ft ²	G	G	N	5
South Play Room	9" x 9" Brown Floor Tile (Under Carpet)	1600 ft ²	C	C	N	5
152-Closet	9" x 9" Brown Floor Tile	48 ft ²	G	G	N	5
169-Storage	9" x 9" Brown Floor Tile	150 ft ²	G	G	N	5
Nurses Area (129)	9" x 9" Brown Floor Tile (Under 12" Tan Floor Tile)	432 ft ²	MD (2 ft ²)	C	N	5
Office Area	12" White Blue Spec Floor Tile	140 ft ²	G	G	N	5
	9" x 9" Brown Floor Tile (Assumed Under 12" Tile)	140 ft ²	C	C	N	5
127A-Closet	9" x 9" Brown Floor Tile	24 ft ²	G	G	N	5
Principal (126)	9" x 9" Brown Floor Tile (Assumed Under Carpet)	154 ft ²	C	C	N	5
Teachers Room (121)(43)	9" x 9" Brown Floor Tile (Under 12" Tan Floor Tile)	648 ft ²	MD (4 ft ²)	C	N	5
Conference Room (119) (27)	9" x 9" Brown Floor Tile (Under 12" Tan Floor Tile)	572 ft ²	MD (2 ft ²)	C	N	5
	Interior Window Glazing	120 lf	G	G	N	5
Receiving Storage Room (153)	9" x 9" Brown Floor Tile	112 ft ²	G	G	N	5
	Pipe Insulation	10 lf	G	G	N	5

Appendix A
AHERA Inspection May 2024
Locations of the Identified Asbestos-Containing Materials
Wampatuck Elementary School-266 Tilden Road

Location	ACM Description	Estimated Quantity	VERTEX 2021 Cond.	VERTEX 2024 Updated Cond.	Fri.	HA #
<i>First Floor (Continued)</i>						
Room 18 (204)	12" x 12" Marble/Tan Floor Tile (Under 12" Tan Floor Tile)	900 ft ²	MD (30 ft ²)	C	N	5
	Black Floor Tile Mastic	900 ft ²	C	C	N	5
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Black Sink Mastic	1 Unit	G	G	N	5
Room 19 (202)	12" x 12" Marble/Tan Floor Tile (Under 12" Tan Floor Tile)	900 ft ²	G	C	N	5
	Black Floor Tile Mastic	900 ft ²	C	C	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Black Sink Mastic	1 Unit	G	G	N	5
Room 20 (201)	12" x 12" Marble/Tan Floor Tile (Under 12" Tan Floor Tile)	900 ft ²	G	C	N	5
	Black Floor Tile Mastic	900 ft ²	C	C	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Black Sink Mastic	1 Unit	G	G	N	5
Room 21 (203)	12" x 12" Marble/Tan Floor Tile (Under 12" Tan Floor Tile)	900 ft ²	G	C	N	5
	Black Floor Tile Mastic	900 ft ²	C	C	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Black Sink Mastic	1 Unit	G	G	N	5
Room 22 (205)	12" x 12" Marble/Tan Floor Tile (Under 12" Tan Floor Tile)	900 ft ²	G	C	N	5
	Black Floor Tile Mastic	900 ft ²	C	C	U	U
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Black Sink Mastic	1 Unit	G	G	N	5
Speech	12" x 12" Off-White Gray Spec Floor Tile (Under 12" Tan FT)	616 ft ²	G	C	N	5
	Black Floor Tile Mastic	616 ft ²	C	C	N	5
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
AV Storage	12" x 12" Marble/Tan Floor Tile (Under 12" Tan Floor Tile)	176 ft ²	G	C	N	5
	Black Floor Tile Mastic	176 ft ²	C	C	N	5
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U



Appendix A
AHERA Inspection May 2024
Locations of the Identified Asbestos-Containing Materials
Wampatuck Elementary School-266 Tilden Road

Location	ACM Description	Estimated Quantity	VERTEX 2021 Cond.	VERTEX 2024 Updated Cond.	Fri.	HA #
<i>First Floor (Continued)</i>						
Library Office	12" x 12" Marble/Tan Floor Tile (Under 12" Tan Floor Tile)	121 ft ²	G	C	N	5
	Black Floor Tile Mastic	121 ft ²	C	C	N	5
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Black Sink Mastic	1 Unit	G	G	N	5
Work Room	12" x 12" Marble/Tan Floor Tile (Under 12" Tan Floor Tile)	154 ft ²	G	C	N	5
	Black Floor Tile Mastic	154 ft ²	C	C	N	5
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
220-Custodial	12" x 12" Marble/Tan Floor Tile	108 ft ²	MD (6 ft ²)	SD (100 ft ²)	N	5
	Black Floor Tile Mastic	108 ft ²	C	Exposed	N	5
	Pipe Fitting Insulation	4 Units	G	G	Y	5
Room 23 (213)	12" x 12" Marble/Tan Floor Tile (Under 12" Tan Floor Tile)	900 ft ²	G	C	N	5
	Black Floor Tile Mastic	900 ft ²	C	C	N	5
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Black Sink Mastic	1 Unit	G	G	N	5
Room 24 (215)	12" x 12" Marble/Tan Floor Tile (Under 12" Tan Floor Tile)	900 ft ²	G	C	N	5
	Black Floor Tile Mastic	900 ft ²	C	C	N	5
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Black Sink Mastic	1 Unit	G	G	N	5
222	12" x 12" Off-White Gray Spec Floor Tile (Under 12" Tan FT)	280 ft ²	G	C	N	5
	Black Floor Tile Mastic	280 ft ²	C	C	N	5
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
224	12" x 12" Off-White Gray Spec Floor Tile (Under 12" Tan FT)	196 ft ²	G	C	N	5
	Black Floor Tile Mastic	196 ft ²	C	C	N	5
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U



Appendix A AHERA Inspection May 2024 Locations of the Identified Asbestos-Containing Materials Wampatuck Elementary School-266 Tilden Road						
Location	ACM Description	Estimated Quantity	VERTEX 2021 Cond.	VERTEX 2024 Updated Cond.	Fri.	HA #
<i>First Floor (Continued)</i>						
Room 25	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	1204 ft ²	MD (3 ft ²)	C	N	6
	Black Floor Tile Mastic	1204 ft ²	C	C	N	5
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Black Sink Mastic	2 Units	G	G	N	5
Room 25-26 Hall	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	40 ft ²	G	C	N	5
	Black Floor Tile Mastic	40 ft ²	C	C	N	5
Room 26	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	1204 ft ²	MD (3 ft ²)	C	N	6
	Black Floor Tile Mastic	1204 ft ²	C	C	N	5
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U	U	U	U
	Black Sink Mastic	2 Units	G	G	N	5

Notes:

ft² = Square Foot
 lf = Linear Foot
 Unit = Each
 Y= Yes
 N = No

Cond. = Condition
 G = Good
 MD = Minor Damage
 D = Damaged
 Fri. = Friable

U = Unknown
 C = Covered
 M = Miscellaneous
 S= Surfacing
 TSI = Thermal System Insulation

NA = Not Accessible



HA # = Homogenous Area Hazard Assessment Category

- 1 = Damaged/Significantly Damaged Thermal System Insulation
- 2 = Damaged Friable Surfacing ACBM
- 3 = Significantly Damaged Friable Surfacing ACBM
- 4 = Damaged or Significantly Damaged Friable Miscellaneous ACBM
- 5 = ACBM with Potential for Damage
- 6 = ACBM with Potential for Significant Damage
- 7 = Any Remaining Friable ACBM or Friable Suspected ACBM
- NA = Not Applicable

APPENDIX B

ESTIMATED RESOURCES REQUIRED TO COMPLETE THE RESPONSE ACTIONS

Appendix B
AHERA Inspection May 2024
Estimated Resources to Complete Response Actions
Wampatuck Elementary School-266 Tilden Road

Location	ACM Description	Estimated Quantity	Recommended Response Action	Estimated Cost	Recommended Completion Date of Response Action	Date of Completed Response Action
<i>First Floor</i>						
Kitchen Office	Pipe Fitting Insulation	3 Units	Repair	\$75.00	August 2024	
220-Custodial	12" x 12" Marble/Tan Floor Tile and Mastic	108 ft ²	Remove/Replace	\$1,000.00	August 2024	

Notes:
 ft² = Square Foot
 Unit = Each

* The estimated cost provided above is developed from current Abatement Contractor Unit pricing. These estimates will vary according to competitive bidding, accessibility, location, and condition of ACMs, phasing of work, etc. In addition, the costs above do not include mobilization of the Abatement Contractor, Abatement Work Plan/Design, Project Monitoring and/or Clearance Testing Services for the completion of the response actions. Please refer for below unit pricing regarding costs for the Contractor Mobilization and Clearance Testing Services:

Abatement Work Plan/Design Specification = \$500-\$2,500.00
 Abatement Contactor Mobilization = \$1,500.00-\$2,500.00
 Project Monitoring/Clearance Testing = \$520.00-\$760.00/per shift
 Transmission Electron Microcopy (TEM) Analysis = \$75.00-\$100.00/sample
 Phase Contrast Microscopy (PCM) Analysis = No Charge -\$15.00/sample
 Clearance Report Preparation = \$350.00-\$800.00

**The estimated cost provided above does not include costs that may be associated with two-hour asbestos awareness training, OSHA 16-hr Operations and Maintenance Training, and/or the labor to conduct the required six-month surveillance re-inspections. Please refer below for estimated costs that may be associated with the mentioned above:



Wampanoag Elementary School

266 Tilden Road

Project # 96632

2-Hour Asbestos Awareness Training = \$75/person

OSHA 16-hr Operations and Maintenance Training = \$300/person

Six-Month Periodic Surveillance Inspection = \$400/inspection

Response Actions

Page 2

APPENDIX C

ESTIMATED RESOURCES REQUIRED FOR THE ABATEMENT OF THE IDENTIFIED ACMs

Appendix C AHERA Inspection May 2024 Estimated Costs for the Removal of the Identified Asbestos-Containing Materials Wampatuck Elementary School-266 Tilden Road			
Location	ACM Description	Estimated Quantity	Estimated Costs
<i>First Floor</i>			
Room 1 (101)	9" x 9" Tan Floor Tile	890 ft ²	\$8,010.00
	Pipe Insulation (Assumed Above Ceiling)	lf	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00
	Cementitious Panel Above Door	6 ft ²	\$60.00
Room 2 (105)	9" x 9" Tan Floor Tile	890 ft ²	\$8,010.00
	Pipe Insulation (Assumed Above Ceiling)	lf	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00
	Cementitious Panel Above Door	6 ft ²	\$60.00
105B	9" x 9" Brown Floor Tile	48 ft ²	\$432.00
Room 3 (102)	9" x 9" Tan Floor Tile	890 ft ²	\$8,010.00
	Pipe Insulation (Assumed Above Ceiling)	lf	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00
	Cementitious Panel Above Door	6 ft ²	\$60.00
102B	9" x 9" Brown Floor Tile	48 ft ²	\$432.00
Room 4 (106)	9" x 9" Tan Floor Tile	890 ft ²	\$8,010.00
	Pipe Insulation (Assumed Above Ceiling)	lf	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00
	Cementitious Panel Above Door	6 ft ²	\$60.00

Appendix C			
AHERA Inspection May 2024			
Estimated Costs for the Removal of the Identified Asbestos-Containing Materials			
Wampatuck Elementary School-266 Tilden Road			
Location	ACM Description	Estimated Quantity	Estimated Costs
<i>First Floor (Continued)</i>			
Room 5 (103)	9" x 9" Tan Floor Tile	890 ft ²	\$8,010.00
	Pipe Insulation (Assumed Above Ceiling)	lf	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00
	Cementitious Panel Above Door	6 ft ²	\$60.00
103B	9" x 9" Brown Floor Tile	48 ft ²	\$432.00
Room 6 (107)	9" x 9" Tan Floor Tile	890 ft ²	\$8,010.00
	Pipe Insulation (Assumed Above Ceiling)	lf	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00
	Cementitious Panel Above Door	6 ft ²	\$60.00
107B	9" x 9" Brown Floor Tile	48 ft ²	\$432.00
Room 7 (104)	9" x 9" Tan Floor Tile	890 ft ²	\$8,010.00
	Pipe Insulation (Assumed Above Ceiling)	lf	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00
	Cementitious Panel Above Door	6 ft ²	\$60.00
Room 8 (108)	9" x 9" Tan Floor Tile	890 ft ²	\$8,010.00
	Pipe Insulation (Assumed Above Ceiling)	lf	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00
	Cementitious Panel Above Door	6 ft ²	\$60.00
North Boys Room (110)	Interior Window Glazing	12 lf	\$120.00
North Girls Room (113)	Interior Window Glazing	12 lf	\$120.00
North Storage (115)	9" x 9" Brown Floor Tile	120 ft ²	\$1,080.00
116	9" x 9" Brown Floor Tile	264 ft ²	\$2,376.00

Appendix C			
AHERA Inspection May 2024			
Estimated Costs for the Removal of the Identified Asbestos-Containing Materials			
Wampatuck Elementary School-266 Tilden Road			
Location	ACM Description	Estimated Quantity	Estimated Costs
<i>First Floor (Continued)</i>			
114	9" x 9" Brown Floor Tile	72 ft ²	\$648.00
112	9" x 9" Brown Floor Tile	20 ft ²	\$180.00
111	9" x 9" Brown Floor Tile	20 ft ²	\$180.00
North Hallway	9" x 9" Green Floor Tile	476 ft ²	\$4,284.00
	Drywall/Joint Compound	720 ft ²	\$4,320.00
Room 117	9" x 9" Green Floor Tile	500 ft ²	\$4,500.00
	Drywall/Joint Compound	720 ft ²	\$4,320.00
Room 9 (133)	9" x 9" Tan Floor Tile	900 ft ²	\$8,100.00
	Pipe Insulation (Assumed Above Ceiling)	If	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00
138	9" x 9" Brown Floor Tile	40 ft ²	\$360.00
Room 10	9" x 9" Tan Floor Tile	900 ft ²	\$8,100.00
	Pipe Insulation (Assumed Above Ceiling)	If	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00
137	9" x 9" Brown Floor Tile	40 ft ²	\$360.00
Room 11	9" x 9" Tan Floor Tile	900 ft ²	\$8,100.00
	Pipe Insulation (Assumed Above Ceiling)	If	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00
Room 12 (143)	9" x 9" Tan Floor Tile	900 ft ²	\$8,100.00
	Pipe Insulation (Assumed Above Ceiling)	If	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00



Appendix C			
AHERA Inspection May 2024			
Estimated Costs for the Removal of the Identified Asbestos-Containing Materials			
Wampatuck Elementary School-266 Tilden Road			
Location	ACBM Description	Estimated Quantity	Estimated Costs
<i>First Floor (Continued)</i>			
146	9" x 9" Brown Floor Tile	168 ft ²	\$1,512.00
Kitchen	Corkboard and Adhesive	70 ft ²	\$420.00
Kitchen Office	Pipe Insulation	30 lf	\$750.00
	Pipe Fitting Insulation	3 Units	\$75.00
Cafetorium	12" x 12" White Floor Tile	3000 ft ²	\$27,000.00
	Black Floor Tile Mastic	3000 ft ²	
	Cementitious Panel Above Doors	42 ft ²	\$420.00
Room 13 (165)	12" White Blue Spec Floor Tile	900 ft ²	\$9,900.00
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	900 ft ²	
	Pipe Insulation (Assumed Above Ceiling)	lf	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00
Room 14 (164)	12" White Blue Spec Floor Tile	900 ft ²	\$9,900.00
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	900 ft ²	
	Pipe Insulation (Assumed Above Ceiling)	lf	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00
Room 15 (163)	12" White Blue Spec Floor Tile	900 ft ²	\$9,900.00
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	900 ft ²	
	Pipe Insulation (Assumed Above Ceiling)	lf	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00
Room 16	12" White Blue Spec Floor Tile	900 ft ²	\$9,900.00
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	900 ft ²	
	Pipe Insulation (Assumed Above Ceiling)	lf	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Chalkboard	88 ft ²	\$880.00



Appendix C			
AHERA Inspection May 2024			
Estimated Costs for the Removal of the Identified Asbestos-Containing Materials			
Wampatuck Elementary School-266 Tilden Road			
Location	ACM Description	Estimated Quantity	Estimated Costs
<i>First Floor (Continued)</i>			
Room 16.1	12" White Blue Spec Floor Tile	64 ft ²	\$704.00
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	64 ft ²	
	Pipe Insulation	20 lf	\$500.00
	Pipe Fitting Insulation	3 Units	\$75.00
Room 17 (162)	Mosaic Pattern Sheet Flooring	1156 ft ²	\$10,404.00
South Play Room	9" x 9" Brown Floor Tile (Under Carpet)	1600 ft ²	\$14,400.00
Nurses Area (129)	9" x 9" Brown Floor Tile	432 ft ²	\$3,888.00
Office Area	12" White Blue Spec Floor Tile	140 ft ²	\$1,260.00
	9" x 9" Brown Floor Tile (Assumed Under 12" Tile)	140 ft ²	\$1,540.00
127A-Closet	9" x 9" Brown Floor Tile	24 ft ²	\$216.00
	9" x 9" Brown Floor Tile (Assumed Under Carpet)	154 ft ²	\$1,386.00
Teachers Room (121)	9" x 9" Brown Floor Tile	648 ft ²	\$5,832.00
Conference Room (119)	9" x 9" Brown Floor Tile	572 ft ²	\$5,148.00
	Interior Window Glazing	120 lf	\$1,200.00
Receiving Storage Room (153)	9" x 9" Brown Floor Tile	112 ft ²	\$1,008.00
	Pipe Insulation	10 lf	\$250.00
Room 18 (204)	12" x 12" Marble/Tan Floor Tile	900 ft ²	\$8,100.00
	Black Floor Tile Mastic	900 ft ²	\$0.00
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	\$0.00
	Black Sink Mastic	1 Unit	\$50.00
Room 19 (202)	12" x 12" Marble/Tan Floor Tile	900 ft ²	\$8,100.00
	Black Floor Tile Mastic	900 ft ²	\$0.00
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	\$0.00
	Black Sink Mastic	1 Unit	\$50.00

Appendix C			
AHERA Inspection May 2024			
Estimated Costs for the Removal of the Identified Asbestos-Containing Materials			
Wampatuck Elementary School-266 Tilden Road			
Location	ACM Description	Estimated Quantity	Estimated Costs
<i>First Floor (Continued)</i>			
Room 20 (201)	12" x 12" Marble/Tan Floor Tile	900 ft ²	\$8,100.00
	Black Floor Tile Mastic	900 ft ²	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Black Sink Mastic	1 Unit	\$50.00
Room 21 (203)	12" x 12" Marble/Tan Floor Tile	900 ft ²	\$8,100.00
	Black Floor Tile Mastic	900 ft ²	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Black Sink Mastic	1 Unit	\$50.00
Room 22 (205)	12" x 12" Marble/Tan Floor Tile	900 ft ²	\$8,100.00
	Black Floor Tile Mastic	900 ft ²	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Black Sink Mastic	1 Unit	\$50.00
Speech	12" x 12" Off-White Gray Spec Floor Tile	616 ft ²	\$5,544.00
	Black Floor Tile Mastic	616 ft ²	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
AV Storage	12" x 12" Marble/Tan Floor Tile	176 ft ²	\$1,584.00
	Black Floor Tile Mastic	176 ft ²	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
Library Office	12" x 12" Marble/Tan Floor Tile	121 ft ²	\$1,089.00
	Black Floor Tile Mastic	121 ft ²	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Black Sink Mastic	1 Unit	\$50.00
Work Room	12" x 12" Marble/Tan Floor Tile	154 ft ²	\$1,386.00
	Black Floor Tile Mastic	154 ft ²	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	



Appendix C			
AHERA Inspection May 2024			
Estimated Costs for the Removal of the Identified Asbestos-Containing Materials			
Wampatuck Elementary School-266 Tilden Road			
Location	ACM Description	Estimated Quantity	Estimated Costs
<i>First Floor (Continued)</i>			
220-Custodial	12" x 12" Marble/Tan Floor Tile	108 ft ²	\$972.00
	Black Floor Tile Mastic	108 ft ²	
	Pipe Fitting Insulation	4 Units	\$100.00
Room 23 (213)	12" x 12" Marble/Tan Floor Tile	900 ft ²	\$8,100.00
	Black Floor Tile Mastic	900 ft ²	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Black Sink Mastic	1 Unit	\$50.00
Room 24 (215)	12" x 12" Marble/Tan Floor Tile	900 ft ²	\$8,100.00
	Black Floor Tile Mastic	900 ft ²	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Black Sink Mastic	1 Unit	\$50.00
222	12" x 12" Off-White Gray Spec Floor Tile	280 ft ²	\$2,520.00
	Black Floor Tile Mastic	280 ft ²	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
224	12" x 12" Off-White Gray Spec Floor Tile	196 ft ²	\$1,764.00
	Black Floor Tile Mastic	196 ft ²	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
Room 25	12" x 12" Marble/Tan Floor Tile	1204 ft ²	\$10,836.00
	Black Floor Tile Mastic	1204 ft ²	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Black Sink Mastic	2 Units	\$100.00
Room 25-26 Hall	12" x 12" Marble/Tan Floor Tile	40 ft ²	\$360.00
	Black Floor Tile Mastic	40 ft ²	
Room 26	12" x 12" Marble/Tan Floor Tile	1204 ft ²	\$10,836.00
	Black Floor Tile Mastic	1204 ft ²	
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	
	Black Sink Mastic	2 Units	\$100.00



Notes:

ft² = Square Foot

lf = Linear Foot

Unit = Each

* The estimated cost provided above is developed from current Abatement Contractor Unit pricing. These estimates will vary according to competitive bidding, accessibility, location, and condition of ACMs, phasing of work, etc. The estimated cost for floor tile mastic removal is included within the total cost for the removal of the associated floor tile. In addition, the costs above do not include mobilization of the Abatement Contractor, Abatement Work Plan/Design, Project Monitoring and/or Clearance Testing Services for the completion of the response actions. Please refer for below unit pricing regarding costs for the Contractor Mobilization and Clearance Testing Services:

Abatement Work Plan/Design Specification = \$500-\$2,500.00

Abatement Contactor Mobilization = \$1,500.00-\$2,500.00

Project Monitoring/Clearance Testing = \$520.00-\$600.00/per shift

Transmission Electron Microcopy (TEM) Analysis = \$75.00-\$100.00/sample

Phase Contrast Microscopy (PCM) Analysis = No Charge -\$15.00/sample

Clearance Report Preparation = \$350.00-\$800.00

APPENDIX D
PERSONNEL CERTIFICATIONS

THE VERTEX COMPANIES, LLC

ACCREDITATION PAGE

Accredited Inspector

Name: Jason Mohre

Accreditation Number: AI000262



Signature: _____

Date: 6/14/2024

Accredited Management Planner

Name: Jason Mohre

Accreditation Number: AP000080




Signature: _____

Date: 6/14/2024

APPENDIX E

SCHEMATIC

Wampanoag Elementary School
266 Tilden Road
Scituate, MA



APPENDIX F

SIX-MONTH SURVEILLANCE FORMS

AHERA Six-Month Surveillance Inspection Date: _____

(Print Name): _____

Signature: _____

Wampatuck Elementary School-266 Tilden Road

Location	ACM Description	Estimated Quantity	May 2024 Cond.	Nov. 2024 Cond.	May 2025 Cond.	Nov. 2025 Cond.	May 2026 Cond.	Nov. 2026 Cond.
<i>First Floor</i>								
Room 1 (101)	9" x 9" Tan Floor Tile (Under 12" Tan FT)	890 ft ²	C					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					
	Cementitious Panel Above Door	6 ft ²	G					
Room 2 (105)	9" x 9" Tan Floor Tile (Under 12" Tan FT)	890 ft ²	C					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					
	Cementitious Panel Above Door	6 ft ²	G					
105B	9" x 9" Brown Floor Tile (Under 12" Tan FT)	48 ft ²	C					
Room 3 (102)	9" x 9" Tan Floor Tile	890 ft ²	G					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					
	Cementitious Panel Above Door	6 ft ²	G					
102B	9" x 9" Tan Floor Tile (Under 12" Tan FT)	48 ft ²	C					
Room 4 (106)	9" x 9" Tan Floor Tile (Under 12" Tan FT)	890 ft ²	G					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					
	Cementitious Panel Above Door	6 ft ²	G					

AHERA Six-Month Surveillance Inspection Date: _____

(Print Name): _____

Signature: _____

Wampatuck Elementary School-266 Tilden Road

Location	ACM Description	Estimated Quantity	May 2024 Cond.	Nov. 2024 Cond.	May 2025 Cond.	Nov. 2025 Cond.	May 2026 Cond.	Nov. 2026 Cond.
<i>First Floor (Continued)</i>								
Room 5 (103)	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	890 ft ²	C					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					
	Cementitious Panel Above Door	6 ft ²	G					
103B	9" x 9" Brown Floor Tile (Under 12" Tan Floor Tile)	48 ft ²	C					
Room 6 (107)	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	890 ft ²	C					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					
	Cementitious Panel Above Door	6 ft ²	G					
107B	9" x 9" Brown Floor Tile (Under 12" Tan Floor Tile)	48 ft ²	C					
Room 7 (104)	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	890 ft ²	C					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					
	Cementitious Panel Above Door	6 ft ²	G					
Room 8 (108)	9" x 9" Tan Floor Tile (Under 12" Tan Floor Tile)	890 ft ²	C					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					
	Cementitious Panel Above Door	6 ft ²	G					
North Boys Room (110)	Interior Window Glazing	12 lf	G					
North Girls Room (113)	Interior Window Glazing	12 lf	G					
North Storage (115)	9" x 9" Brown Floor Tile	120 ft ²	G					
116	9" x 9" Brown Floor Tile	264 ft ²	G					

AHERA Six-Month Surveillance Inspection Date: _____

(Print Name): _____

Signature: _____

Wampatuck Elementary School-266 Tilden Road

Location	ACM Description	Estimated Quantity	May 2024 Cond.	Nov. 2024 Cond.	May 2025 Cond.	Nov. 2025 Cond.	May 2026 Cond.	Nov. 2026 Cond.
<i>First Floor (Continued)</i>								
114	9" x 9" Brown Floor Tile	72 ft ²	G					
112	9" x 9" Brown Floor Tile	20 ft ²	G					
111	9" x 9" Brown Floor Tile	20 ft ²	G					
North Hallway	9" x 9" Green Floor Tile	476 ft ²	G					
	Drywall/Joint Compound	720 ft ²	G					
Room 117	9" x 9" Green Floor Tile (Under 12" Tan FT)	500 ft ²	C					
	Drywall/Joint Compound	720 ft ²	G					
Room 9 (133)	9" x 9" Tan Floor Tile (Under 12" Tan FT)	900 ft ²	C					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					
138	9" x 9" Brown Floor Tile	40 ft ²	G					
Room 10	9" x 9" Tan Floor Tile (Under 12" Tan FT)	900 ft ²	C					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					
137	9" x 9" Brown Floor Tile	40 ft ²	G					
Room 11	9" x 9" Tan Floor Tile (Under 12" Tan FT)	900 ft ²	C					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					
Room 12 (143)	9" x 9" Tan Floor Tile (Under 12" Tan FT)	900 ft ²	G					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					

AHERA Six-Month Surveillance Inspection Date: _____

(Print Name): _____

Signature: _____

Wampatuck Elementary School-266 Tilden Road

Location	ACM Description	Estimated Quantity	May 2024 Cond.	Nov. 2024 Cond.	May 2025 Cond.	Nov. 2025 Cond.	May 2026 Cond.	Nov. 2026 Cond.
<i>First Floor (Continued)</i>								
146	9" x 9" Brown Floor Tile	168 ft ²	G					
Kitchen	Corkboard and Adhesive	70 ft ²	C					
Kitchen Office	Pipe Insulation	30 lf	G					
	Pipe Fitting Insulation	3 Units	MD (3)					
Cafetorium	12" x 12" White Floor Tile	3000 ft ²	G					
	Black Floor Tile Mastic	3000 ft ²	C					
	Cementitious Panel Above Doors	42 ft ²	G					
Room 13 (165)	12" White Blue Spec Floor Tile	900 ft ²	G					
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	900 ft ²	C					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					
Room 14 (164)	12" White Blue Spec Floor Tile	900 ft ²	G					
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	900 ft ²	C					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					
Room 15 (163)	12" White Blue Spec Floor Tile	900 ft ²	G					
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	900 ft ²	C					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					
Room 16	12" White Blue Spec Floor Tile	900 ft ²	G					
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	900 ft ²	C					
	Pipe Insulation (Assumed Above Ceiling)	lf	U					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Chalkboard	88 ft ²	G					

AHERA Six-Month Surveillance Inspection Date: _____

(Print Name): _____

Signature: _____

Wampatuck Elementary School-266 Tilden Road

Location	ACM Description	Estimated Quantity	May 2024 Cond.	Nov. 2024 Cond.	May 2025 Cond.	Nov. 2025 Cond.	May 2026 Cond.	Nov. 2026 Cond.
<i>First Floor (Continued)</i>								
Room 16.1	12" White Blue Spec Floor Tile	64 ft ²	G					
	9" x 9" Tan Floor Tile (Assumed Under 12" Tile)	64 ft ²	C					
	Pipe Insulation	20 lf	G					
	Pipe Fitting Insulation	3 Units	G					
Room 17 (162)	Mosaic Pattern Sheet Flooring	1156 ft ²	G					
South Play Room	9" x 9" Brown Floor Tile (Under Carpet)	1600 ft ²	C					
152-Closet	9" x 9" Brown Floor Tile	48 ft ²	G					
169-Storage	9" x 9" Brown Floor Tile	150 ft ²	G					
Nurses Area (129)	9" x 9" Brown Floor Tile (Under 12" Tan Floor Tile)	432 ft ²	C					
Office Area	12" White Blue Spec Floor Tile	140 ft ²	G					
	9" x 9" Brown Floor Tile (Assumed Under 12" Tile)	140 ft ²	C					
127A-Closet	9" x 9" Brown Floor Tile	24 ft ²	G					
Principal (126)	9" x 9" Brown Floor Tile (Assumed Under Carpet)	154 ft ²	C					
Teachers Room (121)	9" x 9" Brown Floor Tile (Under 12" Tan Floor Tile)	648 ft ²	C					
Conference Room (119)	9" x 9" Brown Floor Tile (Under 12" Tan Floor Tile)	572 ft ²	C					
	Interior Window Glazing	120 lf	G					
Receiving Storage Room (153)	9" x 9" Brown Floor Tile	112 ft ²	G					
	Pipe Insulation	10 lf	G					
Room 18 (204)	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	900 ft ²	C					
	Black Floor Tile Mastic	900 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Black Sink Mastic	1 Unit	G					

AHERA Six-Month Surveillance Inspection Date: _____

(Print Name): _____

Signature: _____

Wampatuck Elementary School-266 Tilden Road

Location	ACM Description	Estimated Quantity	May 2024 Cond.	Nov. 2024 Cond.	May 2025 Cond.	Nov. 2025 Cond.	May 2026 Cond.	Nov. 2026 Cond.
First Floor (Continued)								
Room 19 (202)	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	900 ft ²	C					
	Black Floor Tile Mastic	900 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Black Sink Mastic	1 Unit	G					
Room 20 (201)	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	900 ft ²	C					
	Black Floor Tile Mastic	900 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Black Sink Mastic	1 Unit	G					
Room 21 (203)	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	900 ft ²	C					
	Black Floor Tile Mastic	900 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Black Sink Mastic	1 Unit	G					
Room 22 (205)	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	900 ft ²	C					
	Black Floor Tile Mastic	900 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Black Sink Mastic	1 Unit	G					
Speech	12" x 12" Off-White Gray Spec FT (Under 12" Tan FT)	616 ft ²	C					
	Black Floor Tile Mastic	616 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
AV Storage	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	176 ft ²	G					
	Black Floor Tile Mastic	176 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
Library Office	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	121 ft ²	C					
	Black Floor Tile Mastic	121 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Black Sink Mastic	1 Unit	G					

AHERA Six-Month Surveillance Inspection Date: _____

(Print Name): _____

Signature: _____

Wampatuck Elementary School-266 Tilden Road

Location	ACM Description	Estimated Quantity	May 2024 Cond.	Nov. 2024 Cond.	May 2025 Cond.	Nov. 2025 Cond.	May 2026 Cond.	Nov. 2026 Cond.
<i>First Floor (Continued)</i>								
Work Room	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	154 ft ²	C					
	Black Floor Tile Mastic	154 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
220-Custodial	12" x 12" Marble/Tan Floor Tile	108 ft ²	SD (108 ft ²)					
	Black Floor Tile Mastic	108 ft ²	Exposed					
	Pipe Fitting Insulation	4 Units	G					
Room 23 (213)	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	900 ft ²	C					
	Black Floor Tile Mastic	900 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Black Sink Mastic	1 Unit	G					
Room 24 (215)	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	900 ft ²	G					
	Black Floor Tile Mastic	900 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Black Sink Mastic	1 Unit	G					
222 (31)	12" x 12" Off-White Gray Spec FT (Under 12" Tan FT)	280 ft ²	G					
	Black Floor Tile Mastic	280 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
224 (30)	12" x 12" Off-White Gray Spec FT (Under 12" Tan FT)	196 ft ²	C					
	Black Floor Tile Mastic	196 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
Room 25	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	1204 ft ²	MD (3 ft ²)					
	Black Floor Tile Mastic	1204 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Black Sink Mastic	2 Units	G					
Room 25-26 Hall	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	40 ft ²	G					
	Black Floor Tile Mastic	40 ft ²	C					

AHERA Six-Month Surveillance Inspection Date: _____

(Print Name): _____

Signature: _____

Wampatuck Elementary School-266 Tilden Road

Location	ACM Description	Estimated Quantity	May 2024 Cond.	Nov. 2024 Cond.	May 2025 Cond.	Nov. 2025 Cond.	May 2026 Cond.	Nov. 2026 Cond.
<i>First Floor (Continued)</i>								
Room 26	12" x 12" Marble/Tan Floor Tile (Under 12" Tan FT)	1204 ft ²	C					
	Black Floor Tile Mastic	1204 ft ²	C					
	Pipe Fitting Insulation (Assumed Above Ceiling)	Units	U					
	Black Sink Mastic	2 Units	G					

Notes:

ft² = Square Foot
 lf = Linear Foot
 Unit = Each

Cond. = Condition
 G = Good
 MD = Minor Damage
 D = Damaged

U = Unknown
 C = Covered

NA = Not Accessible

APPENDIX G

DESIGNATED PERSON ASSURANCES

DESIGNATED PERSON ASSURANCES

In accordance with 40 CFR ' 763.93(i) of the Environmental Protection Agency Asbestos-Containing Material in Schools regulation, the undersigned Local Education Agency (LEA) Designated Person (DP) hereby certifies that the following general responsibilities of the LEA under 40 CFR ' 763.84 have been or will be met:

1. Ensure that the activities of any persons who perform inspections, reinspections, and periodic surveillance, develop and update management plans, and develop and implement response actions, including operations and maintenance, are carried out in accordance with Part 763, Subpart E.
2. Ensure that all custodial and maintenance employees are properly trained as required by Part 763, Subpart E and other applicable Federal and/or State regulations (e.g., the Occupational Safety and Health Administration asbestos standard for construction, the EPA worker protection rule, or applicable State regulations).
3. Ensure that workers and building occupants, or their legal guardians, are informed at least once each school year about inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress.
4. Ensure that short-term workers (e.g., telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations for Asbestos-Containing Building Materials (ACBM) and suspected ACBM assumed to be Asbestos-Containing Materials (ACM).
5. Ensure that warning labels are posted in accordance with ' 40 CFR 763.95.
6. Ensure that management plans are available for inspection and notification of such availability has been provided as specified in the management plan under ' 40 CFR 763.93(g).
7. Designate a person to ensure that requirements under ' 763.84 are properly implemented and ensure that the designated person receives adequate training to perform duties assigned under ' 763.84. Such training shall provide, as necessary, basic knowledge of: health effects of asbestos; detection, identification, and assessment of ACM; options for controlling ACBM; asbestos management programs; relevant Federal and State regulations concerning asbestos, including those in Part 763, Subpart E and those of the Occupational Safety and Health Administration, U.S. Department of Transportation and the U.S. Environmental Protection Agency.
8. Consider whether any conflict of interest may arise from the inter-relationship among accredited personnel and whether that should influence the selection of accredited personnel to perform activities under Part 763, Subpart E.

Name of Designated Person:

Christopher Cataldo

Designated Person's Signature:



Date:

8-01-2024