Scituate Public Schools

Cushing -Hatherly Elementary School Project

School Building Committee Public Forum

February 15, 2023



How we got here... Hatherly and Cushing Schools

- Both schools experience space deficiencies in their educational programs, particularly, special education, art, and music.
- Both have inappropriate space adjacencies:
 library, gymnasium
- Each school needs significant upgrades, including HVAC, plumbing, electrical, exterior windows and envelope, accessibility, etc.
- Both have temporary modular classrooms.
- **Hatherly** was determined to be in the most need of the four district elementary schools.



Hatherly Elementary School – 1962 (**61 yrs**)



Cushing Elementary School – 1964 (**59 yrs**)

Existing Conditions Assessment: What is


- Hatherly (1962 61 yrs.) and Cushing (1964 59 yrs.) are "twin schools"
- Nearly identical designs and installed components
- Very similar observations between the two buildings to a greater or lesser degree
- Maintenance has differed over the years, so some replaced components are different
- Neither building has had major upgrades
- Bottom line: both schools have great facilities needs





Existing Conditions Assessment: What is

No major red flags or dangerous safety conditions



Site Issues

- One entry/exit
- Traffic congestion
- Difficult Circulation
- Inadequate Parking
- Paving Condition
- Accessibility issues

Civil/Drainage

- Poor drainage
- Stormwater standards
- Wet fields









Build 1962 Architectural Issues

- Foundations
- Windows
- Panels around windows
- Envelope/ Insulation lacking
- Caulking brittle, cracked
- Modulars deteriorating 20 yrs.









Architectural Issues

- Roof membrane age, condition
- Lack of pitch to drains
- History of leakage
- Eaves and fascias
- Chimney deteriorated
- Lack of roof insulation
- Deck structure not suitable for alterations










Interior Issues

- Lack of temperature control
- Drafty, leaky envelope
- *Tired, worn interiors*
- Dingy ceilings around air grilles
- Accessibility Issues
- Library & Gym location
- VAT present, stable condition
- Structural upgrades required if renovated









Mechanical Issues

- Outdated, mixed controls
- No BMS
- Aging, inefficient steam boilers
- Gas fuel
- Leaking pipes
- Original unit ventilators
- Aging AHUs
- Window AC units
- Lack of mech. ventilation
- Direct exhaust fans added









Electrical Issues

- Original electrical switchgear - systems not suitable for renovation
- Few spare breakers
- Lack of outlets, lots of power strips in use
- Newer generator
- Some newer LED; some older, inefficient lighting
- No lighting controls
- Fire alarm system does not meet present-day code










Plumbing Issues

- Original plumbing fixtures

 not water-efficient
- Many fixtures and faucets not accessible
- Water quality issues building filtration needed
- Gas piping lacks solenoid in kitchen
- Newer gas water heater
- Piping generally past useful life
- *Kitchen lacks interior grease traps*



What can be



Hatherly Elementary School - Library

Sunita L. Williams Elementary School - Library


What can be



Hatherly Elementary School - Corridor

S.L. Williams Elementary School – Extended Learning

What can be



Cushing Elementary School - corridor

Woodland ES, Milford Extended Learning SMMA Architects

What can be



Cushing Elementary School - Cafeteria

Northbridge Elementary School Cafeteria

What can be



Cushing Elementary School - Classroom

West Parish Elementary School